Mr. Robert G. Byram
Senior Vice President-Lear
Pennsylvania Power and Light
Company
2 North Ninth Street
Allentown, PA 18101

SUBJECT: SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1, STAFF ACKNOWLEDGMENT IN REGARD TO PENNSYLVANIA POWER AND LIGHT COMPANY'S (PP&L) SUPPLEMENTAL

RESPONSE TO GENERIC LETTER (GL) 94-03 (TAC NO. M92098)

Dear Mr. Byram:

The following enclosure provides the staff's safety evaluation (SE) regarding PP&L's Interim Response to GL 94-03, "Intergranular Stress Corrosion Cracking of Core Shrouds in Boiling Water Reactors," for the Susquehanna Steam Electric Station Unit 1 (SSES-1), dated April 21, 1995. PP&L's response forwarded the results of the SSES-1 core shroud inspections and flaw evaluations that were performed as part of the licensee's activities during the current the SSES-1 refueling and inspection outage (RIO) 8RIO.

The staff has reviewed the results of examinations and flaw evaluations performed by PP&L during 8RIO in regard to the assessment of the SSES-1 core shroud, and has determined that PP&L has conservatively used the core shroud inspection and flaw evaluation criteria of the BWRVIP as a basis for performing inspections and flaw evaluations of the SSES-1 core shroud. Therefore, the staff concludes that sufficient remaining ligament exists in the SSES-1 core shroud to justify operation of the SSES-1 unit for the next operating cycle, without necessitating an immediate core shroud modification (repair) during the current RIO (No. 8RIO). PP&L will be required to either re-inspect or repair the SSES-1 core shroud during the fall 1996 RIO (No. 9RIO).

Based on its evaluation, the staff has no safety issues regarding the SSES-1 core shroud which would preclude PP&L from restarting the SSES-1 unit. Please contact me at 301-415-1402 or James Medoff at 301-415-2715 if you have any questions regarding the staff evaluation.

Sincerely,
/S/ L. Olshan for
Chester Poslusny, Project Manager
Project Directorate I-2
Division of Reactor Projects - I/II
Office of Nuclear Reactor Regulation

160067

Docket No. 50-387

Enclosure: Safety Evaluation

cc w/encl: See next page

DISTRIBUTION

Docket File JStolz ACRS(4) JStrosnider PUBLIC CPoslusny JWhite, RGN-I JMedoff

PDI-2 Reading MO'Brien RJones SVarga/JZwolinski OGC RWessman

OFFICE		BDI-2/PM	PDI-2/D	,	
NAME	Mo/Boren 9	CPoslusny:rb	JStolz		
DATE	5/2/95	5/3/95	5/3/95		

OFFICIAL RECORD COPY 9505180535 950503 DOCUMENT NAME: SU92098.GEN

DYOI

•



UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

May 3, 1995

Mr. Robert G. Byram Senior Vice President-Nuclear Pennsylvania Power and Light Company 2 North Ninth Street Allentown, PA 18101

SUBJECT: SUSQUEHANNA STEAM ELECTRIC STATION, UNIT 1, STAFF ACKNOWLEDGMENT IN

REGARD TO PENNSYLVANIA POWER AND LIGHT COMPANY'S (PP&L) SUPPLEMENTAL

RESPONSE TO GENERIC LETTER (GL) 94-03 (TAC NO. M92098)

Dear Mr. Byram:

The following enclosure provides the staff's safety evaluation (SE) regarding PP&L's Interim Response to GL 94-03, "Intergranular Stress Corrosión Cracking of Core Shrouds in Boiling Water Reactors," for the Susquehanna Steam Electric Station Unit 1 (SSES-1), dated April 21, 1995. PP&L's response forwarded the results of the SSES-1 core shroud inspections and flaw evaluations that were performed as part of the licensee's activities during the current the SSES-1 refueling and inspection outage (RIO) 8RIO.

The staff has reviewed the results of examinations and flaw evaluations performed by PP&L during 8RIO in regard to the assessment of the SSES-1 core shroud, and has determined that PP&L has conservatively used the core shroud inspection and flaw evaluation criteria of the BWRVIP as a basis for performing inspections and flaw evaluations of the SSES-1 core shroud. Therefore, the staff concludes that sufficient remaining ligament exists in the SSES-1 core shroud to justify operation of the SSES-1 unit for the next operating cycle, without necessitating an immediate core shroud modification (repair) during the current RIO (No. 8RIO). PP&L will be required to either re-inspect or repair the SSES-1 core shroud during the fall 1996 RIO (No. 9RIO).

Based on its evaluation, the staff has no safety issues regarding the SSES-1 core shroud which would preclude PP&L from restarting the SSES-1 unit. Please contact me at 301-415-1402 or James Medoff at 301-415-2715 if you have any questions regarding the staff evaluation.

Chester Poslusny, Project Manager Project Directorate I-2 Division of Reactor Projects - I/II Office of Nuclear Reactor Regulation

Docket No. 50-387

Enclosure: Safety Evaluation

cc w/encl: See next page

Mr. Robert G. Byram Pennsylvania Power & Light Company Susquehanna Steam Electric Station, Units 1 & 2

cc:

Jay Silberg, Esq. Shaw, Pittman, Potts & Trowbridge 2300 N Street N.W. Washington, D.C. 20037

Bryan A. Snapp, Esq.
Assistant Corporate Counsel
Pennsylvania Power & Light Company
2 North Ninth Street
Allentown, Pennsylvania 18101

Mr. J. M. Kenny Licensing Group Supervisor Pennsylvania Power & Light Company 2 North Ninth Street Allentown, Pennsylvania 18101

Mrs. Maitri Banerjee Senior Resident Inspector U. S. Nuclear Regulatory Commission P.O. Box 35 Berwick, Pennsylvania 18603-0035

Mr. William P. Dornsife, Director Bureau of Radiation Protection Pennsylvania Department of Environmental Resources P. O. Box 8469 Harrisburg, Pennsylvania 17105-8469

Mr. Jesse C. Tilton, III Allegheny Elec. Cooperative, Inc. 212 Locust Street P.O. Box 1266 Harrisburg, Pennsylvania 17108-1266 Regional Administrator, Region I U.S. Nuclear Regulatory Commission 475 Allendale Road King of Prussia, Pennsylvania 19406

Mr. Harold G. Stanley Vice President-Nuclear Operations Susquehanna Steam Electric Station Pennsylvania Power and Light Company Box 467 Berwick, Pennsylvania 18603

Mr. Herbert D. Woodeshick Special Office of the President Pennsylvania Power and Light Company Rural Route 1, Box 1797 Berwick, Pennsylvania 18603

George T. Jones Vice President-Nuclear Engineering Pennsylvania Power and Light Company 2 North Ninth Street Allentown, Pennsylvania 18101

Dr. Judith Johnsrud National Energy Committee Sierra Club 433 Orlando Avenue State College, PA 16803

Chairman Board of Supervisors 738 East Third Street Berwick, PA 18603