

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9808060180      DOC.DATE: 98/07/31    NOTARIZED: NO                  DOCKET #  
FACIL:50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylva    05000387  
AUTH.NAME                         AUTHOR AFFILIATION  
KUCZYNSKI,G.J.      Pennsylvania Power & Light Co.  
RECIP.NAME                         RECIPIENT AFFILIATION  
                                     Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-013-00 re panel door removed from halon protected panel, causing halon sys to become inoperable & continuous fire watch not established.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 3  
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

**NOTES :**

05000387E

	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL
	PD1-2 PD	1	1	NERSSES,V	1	1
INTERNAL:	ACRS	1	1	AEOD/SPD/RAB	2	2
	AEOD/SPD/RRAB	1	1	<u>FILE CENTER</u>	1	1
	NRR/DE/ECGB	1	1	NRR/DE/EELB	1	1
	NRR/DE/EMEB	1	1	NRR/DRCH/HICB	1	1
	NRR/DRCH/HOHB	1	1	NRR/DRCH/HQMB	1	1
	NRR/DRPM/PECB	1	1	NRR/DSSA/SPLB	1	1
	RES/DET/EIB	1	1	RGN1 FILE 01	1	1
EXTERNAL:	L ST LOBBY WARD	1	1	LITCO BRYCE, J H	1	1
	NOAC POORE,W.	1	1	NOAC QUEENER,DS	1	1
	NRC PDR	1	1	NUDOCS FULL TXT	1	1
NOTES:		1	1			

**NOTE TO ALL "RIDS" RECIPIENTS:**

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED  
TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 24

George J. Kuczynski  
General Manager-Susquehanna

Susquehanna Steam Electric Station  
P.O. Box 467, Berwick, PA 18603  
Tel. 717.542.3120 Fax 717.542.1949




July 31, 1998

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Mail Station P1-137  
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION  
LICENSEE EVENT REPORT 50-387/98-013-00  
PLA - 0004960 FILE R41-2

Docket No. 50-387  
License No. NPF-14

Attached is Licensee Event Report 50-387/98-013-00. This event was determined to be reportable per 10CFR50.73(a)(2)(i)(B) in that, when a panel door was removed from a halon protected panel, the halon system became inoperable and a continuous fire watch had not been established in accordance with Technical Specification 3.7.6.4 ACTION a. The error was discovered during document review the following morning, after the panel had been restored. The halon system remained capable of performing its function during the time the panel door was removed.

  
G. J. Kuczynski  
General Manager - Susquehanna SES

*JE22/1*

Attachment

cc: Mr. H. J. Miller  
Regional Administrator  
U. S. Nuclear Regulatory Commission  
475 Allendale Road  
King of Prussia, PA 19406

cc: Mr. Kenneth M. Jenison  
Sr. Resident Inspector  
U.S. Nuclear Regulatory Commission  
P. O. Box 35  
Berwick, PA 18603-0035

9808060180 980731  
PDR ADOCK 05000387  
S PDR