

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9904060112 **DOC.DATE:** 99/03/30 **NOTARIZED:** NO **DOCKET #**
FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387
AUTH.NAME **AUTHOR AFFILIATION**
 SAUNDERS, R.F. Pennsylvania Power & Light Co.
RECIP.NAME **RECIPIENT AFFILIATION**
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 99-001-00. Event was determined to be reportable
 per 10CFR50.73(a)(2)(ii) & 10CFR50.73(a)(2)(v) in that both
 loops of LPCI mode of RHRS were inoperable during 17 h time
 period.

DISTRIBUTION CODE: IE22T **COPIES RECEIVED:** LTR 1 ENCL 1 **SIZE:** 1+7
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES: 05000387

	RECIPIENT ID CODE/NAME		COPIES		RECIPIENT ID CODE/NAME		COPIES	
			LTR	ENCL			LTR	ENCL
	PD1-2 PD		1	1	NERSES, V		1	1
INTERNAL:	ACRS		1	1	AEOD/SPD/RAB		2	2
	AEOD/SPD/RRAB		1	1	FILE CENTER		1	1
	NRR/DRCH/HOHB		1	1	NRR/DRCH/HOMB		1	1
	NRR/DRPM/PECB		1	1	NRR/DSSA/SPLB		1	1
	RES/DET/EIB		1	1	RGN1 FILE 01		1	1
EXTERNAL:	L ST LOBBY WARD		1	1	LMITCO MARSHALL		1	1
	NOAC POORE, W.		1	1	NOAC QUEENER, DS		1	1
	NRC PDR		1	1	NUDOCS FULL TXT		1	1
NOTES:			1	1				

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
 OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
 DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTR 20 ENCL 20

AD4



3
2

Robert F. Saunders
Vice President - Nuclear Site Operations

Susquehanna Steam Electric Station.
P.O. Box 467, Berwick, PA 18603
Tel. 717.542.3256 Fax 717.542.1504
rfsaunders@papl.com



March 30, 1999

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-137
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-387/99-001-00
PLA - 0005048 FILE R41-2

Docket No. 50-387
License No. NPF-14

Attached is Licensee Event Report 50-387/99-001-00. This event was determined to be reportable per 10CFR50.73(a)(2)(ii) and 10CFR50.73(a)(2)(v) in that both loops of the Low Pressure Coolant Injection (LPCI) mode of the Residual Heat Removal system were inoperable during a 17 hour time period. This event was also determined to be reportable per 10CFR50.73(a)(2)(i) in that the 'B' Loop of LPCI was inoperable longer than allowed by the Technical Specifications. Both loops have been restored to operable status.

Robert F. Saunders
Vice President - Nuclear Site Operations

Attachment

cc: Mr. H. J. Miller
Regional Administrator
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

cc: Mr. S. L. Hansell
Sr. Resident Inspector
U.S. Nuclear Regulatory Commission
P. O. Box 35
Berwick, PA 18603-0035

9904060112 990330
PDR ADOCK 05000387
S PDR

060026

IE22



1
2