

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9907080343 DOC.DATE: 99/07/01 NOTARIZED: NO DOCKET #
 FACIL: 50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylv 05000387
 AUTH.NAME SAUNDERS, R.F. AUTHOR AFFILIATION Pennsylvania Power & Light Co.
 RECIP.NAME SAUNDERS, R.F. RECIPIENT AFFILIATION Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 99-002-00, re inoperable acoustic monitors for period between 980714 & 981003. Sealant that was required to be applied to accelerometer cable connectors to meet environment qualification design requirements was not applied.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1 + 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

05000387

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	LPD1-1 PD	1 1	NERSES, V	1 1
INTERNAL:	ACRS	1 1	AEOD/SPD/RRAB	1 1
	FILE CENTER	1 1	NRR/DIPM/IOLB	1 1
	NRR/DRIP/REXB	1 1	NRR/DSSA/SPLB	1 1
	RES/DET/EIB	1 1	RGN1 FILE 01	1 1
EXTERNAL:	L ST LOBBY WARD	1 1	LMITCO MARSHALL	1 1
	NOAC POORE, W.	1 1	NOAC QUEENER, DS	1 1
	NRC PDR	1 1	NUDOCS FULL TXT	1 1
NOTES:		1 1		

NOTE TO ALL "RIDS" RECIPIENTS:
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LIST OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 17 ENCL 17

AD4

Robert F. Saunders
Vice President - Nuclear Site Operations

Susquehanna Steam Electric Station.
P.O. Box 467, Berwick, PA 18603
Tel. 717.542.3256 Fax 717.542.1504
rfsaunders@papl.com



JUL 01 1999

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-137
Washington, DC 20555

SUSQUEHANNA STEAM ELECTRIC STATION
LICENSEE EVENT REPORT 50-387/99-002-00
PLA - 5084 FILE R41-2

Docket No. 50-387
License No. NPF-14

Attached is Licensee Event Report 50-387/99-002-00. This event was determined to be reportable per 10CFR50.73(a)(2)(i) in that the acoustic monitors on Unit 1 for the period between July 14, 1998 and October 3, 1998, were determined to have been inoperable because of environmental qualification concerns. Also, the "J" acoustic monitor on Unit 2 was determined to have been inoperable between June 25, 1998 and October 3, 1998 because of environmental qualification concerns. During this period of time, when the acoustic monitors were in the Standard Technical Specifications, a modification was performed on the Unit 1 acoustic monitors and the Unit 2 "J" acoustic monitor. A sealant that was required to be applied to the accelerometer cable connectors to meet environmental qualification design requirements was not applied during the modification. The deficiency was identified on June 2, 1999. The sealant has been applied to the accelerometer cable connectors for both units, and the acoustic monitors are operable.


Robert F. Saunders
Vice President - Nuclear Site Operations

Attachment

cc: Mr. H. J. Miller
Regional Administrator
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406

cc: Mr. S. L. Hansell
Sr. Resident Inspector
U.S. Nuclear Regulatory Commission
P. O. Box 35
Berwick, PA 18603-0035

9907080343 990701
PDR ADDCK 05000387
S PDR