



**Docket File Information**

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  JanX Integrity Group 8550 East Michigan Avenue Parma, MI 49269 Locations: Job Site in Michigan City, Indiana  REPORT NUMBER(S) 2017002	2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
--	---

3. DOCKET NUMBER(S)  030-11772	4. LICENSE NUMBER(S)  21-16560-01	5. DATE(S) OF INSPECTION  May 26, 2017
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED  87121	7. INSPECTION FOCUS AREAS  FE 1 - 6
--	---

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S)  03320	2. PRIORITY  1	3. LICENSEE CONTACT  Steve Flickinger - RSO	4. TELEPHONE NUMBER  (517) 531-8210
---------------------------------	----------------------	---	---

Main Office Inspection                      Next Inspection Date:                                No Change          

Field Office Inspection                      \_\_\_\_\_

Temporary Job Site Inspection              County Line Road at W 300 N, Michigan City, IN          

**PROGRAM SCOPE**

This was an announced field inspection of a large non-destructive testing company authorized to use radioactive material for industrial radiography at numerous field stations and at temporary job sites throughout NRC jurisdiction. At the time of the inspection, the licensee scheduled work, dispatched radiographers, and maintained equipment for operations in northern Indiana out of an office in Mokena, Illinois.

**PERFORMANCE OBSERVATIONS**

The inspector observed the conduct of radiographic operations by two radiography crews on a Northern Indiana Public Service Company natural gas pipeline construction project running from LaPorte, Indiana to Munster, Indiana. The inspector noted the satisfactory set-up and control of restricted area boundaries during these operations, as confirmed by independent surveys and several inadvertent challenges to those boundaries by other workers on the right-of-way. Through interviews, the inspector found that the radiographers and assistants were knowledgeable of radiation protection principles, licensee procedures and regulatory requirements, and that their dosimetry and survey instruments were calibrated, operable, and properly utilized.

While at the job site, the inspector reviewed a selection of available records, including shipping papers and utilization logs. Following the on-site inspection, the inspector reviewed radiographer audits for all five of the individuals observed.

No violations of NRC requirements were identified as a result of this inspection.