

Central
Files
YELLOW FILE COPY

MAY 23 1979

Docket No. 50-237
Docket No. 50-249

Commonwealth Edison Company
ATTN: Mr. Byron Lee, Jr.
Vice President
Post Office Box 767
Chicago, IL 60690

Gentlemen:

This refers to the inspection conducted by Messrs. L. A. Reyes, B. M. K. Wong and R. W. Dettenmeier of this office on March 27, April 13, 21-23 and 27, 1979 and the letter to you from Mr. R. F. Heishman dated May 3, 1979, accompanied by Inspection Report No. 50-237/79-11 and No. 50-249/79-09.

Please find enclosed a corrected copy of page 6 of Inspection Reports No. 50-237/79-11 and No. 50-249/79-09. The typographical error on page 6 corrects the total wt%/day for CILRT valve lineup penalties to 0.1361. The total had erroneously been written as 0.01361. Please replace the former page 6 with the enclosed corrected copy.

Sincerely,

R. F. Heishman, Chief
Reactor Operations and
Nuclear Support Branch

Enclosure: As stated

cc w/encl:
Mr. B. B. Stephenson,
Station Superintendent
Central Files
Reproduction Unit NRC 20b
PDR
Local PDR
NSIC
TIC
Anthony Roisman, Esq., Attorney
Mr. Dean Hansell, Office of
Assistant Attorney General

RIII
Reyes/bk
5/22/79

RIII
Wong
5/24/79

RIII
Dettenmeier
5/22/79

RIII
Streeter
5/22/79

RIII
Heishman
5/22

RIII
Barker

5/21/79

8906230079

Standby Liquid Control	1.26	0.00257
Isolation Condenser	1.61	0.00328
'A' LPCI	9.64	0.01968
'B' LPCI	6.92	0.01413
'A' Core Spray	5.75	0.01174
'B' Core Spray	1.15	0.00234
CAM	0.78	0.00159
Primary Sample	0.02	0.00004
Reactor Cleanup	8.36	0.01707
<u>TOTAL</u>	<u>66.63</u>	<u>0.1361</u>

9. Plant Tour

The inspector conducted a tour of various areas of the plant to observe operations and activities in progress, general house-keeping and cleanliness, and equipment caution or lockout tags.

No items of noncompliance or deviations were identified.

10. Unresolved Items

Unresolved items are matters about which more information is required in order to ascertain whether they are acceptable items, items of noncompliance, or deviations. An unresolved item disclosed during the inspection is discussed in Paragraph 7.

11. Exit Interview

An exit interview was conducted at the conclusion of the inspection with the licensee representatives denoted in Paragraph 1. The total leak rate after all corrections were included was determined by the licensee to be 0.3953 weight percent/day.