

DEC 18 1991

Docket No. 50-249
License No. DPR-25
EA 91-165

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Senior Vice President
Opus West III
1400 Opus Place
Downers Grove, IL 60515

SUBJECT: CHANGE TO NRC INSPECTION REPORT NO. 50-249/91032(DRS)

Dear Mr. Reed:

I am writing to provide you an amended page 7 to Inspection Report No. 249/91032(DRS). The change deletes the reference to Inspection Reports No. 237/91030(DRS) and No. 249/91039(DRS), which have been canceled. Additional NRC review of actions taken in response to the issues identified in Inspection Report No. 249/91032(DRS) will be addressed in subsequent Resident Inspection Reports. Please replace page 7 of your copy of the report with the enclosed page.

We apologize for any inconvenience this may have caused you.

Sincerely,

Hubert J. Miller, Director
Division of Reactor Safety

Enclosure: Page 7 of
Inspection Report
No. 50-249/91032(DRS)

See Attached Distribution

RIII
PRR
Rescheske/cg
12/16/91

RIII
ML
Phillips
12/16/91

RIII
BB
B. Burgess
12/16/91

RIII
AM for
Wright
12/16/91

RIII
VP
Pederson
12/16/91

RIII
AM
Martin
12/16/91

RIII
See Previous Page
Miller
12/ /91

DEC 18 1991

Distribution

cc w/enclosure:

D. Galle, Vice President - BWR
Operations

T. Kovach, Nuclear
Licensing Manager

C. Schroeder, Station Manager
DCD/DCB (RIDS)

OC/LFDCB

Resident Inspectors LaSalle,
Dresden, Quad Cities

Richard Hubbard

J. W. McCaffrey, Chief, Public
Utilities Division

Robert Newmann, Office of Public
Counsel, State of Illinois Center

Licensing Project Manager, NRR

B. Berson, Regional Counsel, RIII

J. Lieberman, OE

J. Goldberg, OGC

J. Partlow, NRR

pending detailed inspections of the fuel handling equipment for missing parts. Initial inspections of the spent fuel racks and the upper tie plates of the affected fuel bundles did not identify additional damage or loose parts from the mast/grapple.

- e. An assessment of fuel assembly damage was conducted by the fuel vendor, who confirmed fuel integrity. The fuel bundles with the damaged bail handles were thrice-burned assemblies which were to be used for Unit 3 reload. While these bundles will not be reused in the reactor, they need to be moved from their current locations in the SFP since they appear to obstruct removal of adjacent bundles required for reload. The Unit 3 core reload design was being revised to replace the two damaged assemblies.

NRC review of the licensee's completed corrective actions and response to the CAL will be addressed in subsequent NRC Resident inspection reports.

6. Exit Meeting

The inspector met with licensee representatives (denoted in Paragraph 1) on November 12, 1991. The inspector summarized the purpose, scope, and findings of the inspection and the likely informational content of the inspection report. The licensee acknowledged this information and did not identify any information as proprietary.