



Commonwealth Edison
Dresden Nuclear Power Station
6500 North Dresden Road
Morris, Illinois 60450
Telephone 815/942-2920

September 21, 1993

GFS GFSLTR 93-0075

U. S. Nuclear Regulatory Commission
Document Control Clerk
Washington, D.C. 20555

This is a supplement to LER 93-012 to change corrective action number 1 used in the original LER. Requiring two persons to install every breaker places an unnecessary workload on operations. When possible, two persons will install the breaker, but in many instances using one qualified individual is sufficient. A review of current and past practices by operations management has determined that the need for two individuals is on a case-by-case basis and the practice of breaker installation will be following in this manner.

Gary F. Spedl
Station Manager
Dresden Station

GFS/klS

cc: J. Martin, Regional Administrator, Region III
File/NRC
File/Numerical

(g:\wpt\cws\l93\346525.po)

270071

9309300001 930921
PDR ADOCK 05000237
S PDR



DAP FORM 02-08C
 SUPPLEMENTAL REPORT TO LER

DVR NO.					SYSTEM AFFECTED	
	STA	UNIT	YEAR	NO.		
D	12	2	93	012	6500	
<u>PART 1</u> TITLE OF EVENT				<u>OCCURRED</u>		
Failure of Unit 2 Emergency Diesel Generator Output Breaker to Close Due to Mechanical Failure				04/18/93		1020
				DATE		TIME
REASON FOR SUPPLEMENTAL REPORT						
Change to Corrective Action Number 1						
<u>PART 2</u>						
ACCEPTANCE BY STATION REVIEW				<u>Stinson</u>		<u>MC Strait</u>
DATE				9/20/93		9/20/93
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION				<u>W. Halpin for</u>		9-21-93
				STATION MANAGER		DATE