

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



October 31, 1995

PGHLTR 95-0026

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Licensee Event Report 95-011, Supplement 1, Docket 50-249 is being submitted pursuant to 10CFR50.73(a)(2)(i) and 10CFR50.73(a)(2)(ii), the reporting of any operation or condition prohibited by the Plant's Technical Specifications.

This supplement provides the cause of the HPCI Turbine Exhaust Check Valve LLRT failure and the corrective actions taken.

This letter contains the following commitments:

- 1) Monitoring of the High Pressure Coolant Injection System Turbine Exhaust to Suppression Pool Check Valve, 3-2301-45, will also be performed during the next HPCI run. Evaluation of the results will determine if additional actions are required. (NTS #249-180-95-01104)
- 2) Replacing the current dual disk check valve, 3-2301-45, with a lift-type check valve is being evaluated. (NTS #249-180-95-01105)
- 3) Evaluation of valve design for the Low Pressure Coolant Injection System Drywell Spray Outboard (3-1501-27A) and Inboard (3-1501-28A) valve is ongoing. (NTS #249-180-95-01106)
- 4) A review of system operation coupled with procedure changes will be performed to ensure that the piping between valves 2(3)-1501-27A(B) and 2(3)-1501-28A(B) remains water filled to minimize pipe corrosion and to prevent corrosion products from coming in contact with the seating surfaces. (NTS #249-180-95-01107)
- 5) Additional evaluations are being performed to refine the dose rate calculations to determine whether or not either GDC 19 limits or 10CFR100 limits would have been exceeded. (NTS #249-180-95-01108)

Sincerely,

Peter G. Holland
Regulatory Assurance Supervisor

PGH/MM:pt
Enclosure

cc: H. Miller, Regional Administrator, Region III
NRC Resident Inspector's Office
File/NRC
File/Numerical