

## UNITED STATES NUCLEAR REGULATORY COMMISSION

WASHINGTON, D.C. 20555-0001

January 29, 1996

Mr. James J. O'Connor Chairman and Chief Executive Officer Commonwealth Edison Company P.O. Box 767 Chicago, IL 60690

Dear Mr. O'Connor:

On January 17-18, 1996, NRC senior managers met to evaluate the nuclear safety performance of operating reactors, fuel facilities and other materials licensees. The NRC conducts this meeting semiannually to determine if the safety performance of various licensees exhibits sufficient weaknesses to warrant increased NRC attention or if it is trending adversely and requires steps to be taken to communicate concerns to the utility's president or board of directors. At the January 1996 Senior Management Meeting (SMM), the Dresden Nuclear Power Station was discussed.

The Dresden Station was placed on the NRC watch list for the second time in January 1992 and remains a Category 2 plant. Plants in this category have been identified as having weaknesses that warrant increased NRC attention until the licensee demonstrates a period of improved performance. A summary of NRC discussions related to Dresden follows:

During the June 1995 SMM, NRC noted that ComEd had lost its momentum in improvement efforts at Dresden. Over the past six months, ComEd has taken steps to regain this momentum. Following a significant event involving violation of technical specification limits at the beginning of 1995, station management refocused attention on operations standards and accountability. As a consequence, marked improvement has been observed in control room activities. While Unit 3 was hampered with equipment problems coming out of an extended forced outage, each of three startup evolutions on the Unit was conducted in a deliberate, error free manner. Priority was given to resolving operator workarounds and control room deficiencies with positive results. Overall, a more conservative approach to decision making has been observed at the station.

Units 2 and 3 were both shutdown for most of the past six months. Unit 2 has been in an extended refueling outage and Unit 3 was shut down to repair a failed turbine generator. Steps were taken to resolve a number of longstanding equipment problems during these outages. However, considerable work remains to be done with respect to material condition. The backlog of equipment deficiencies remains high while problems with work planning and coordination have persisted. Station management acted to improve work control and planning, but significant results have yet to be observed. Weaknesses in worker skill levels continue to hamper progress in this area.

LA3

Df01 10

The number of radiological protection and maintenance related personnel errors also continued to be high, particularly during the dual unit outage, indicating efforts to communicate management standards and expectations have not been fully effective. Engineering support to the station improved through increased staffing and involvement in plant activities but efforts to better identify equipment problems through plant walkdowns and system reviews need to continue.

Continued significant management attention is needed to assure improvement efforts are sustained and effective at Dresden. This is particularly important in light of the long time that Dresden has been a Category 2 plant and its history of cyclic performance. While performance improvements have again been observed in some areas, effectiveness of recent management changes and improvement efforts will only become clear as the Unit 2 outage is completed, the Unit is restarted and operated along with Unit 3 for a period of time.

Mr. Hubert J. Miller, the Region III Administrator, has discussed the bases for our conclusions with members of your staff.

An NRC Commission meeting, open to the public, has been scheduled to be held in the Commissioners' Conference Room in Rockville, Maryland, on January 31, 1996, at 10:00 a.m., to review the results of the latest meeting of NRC senior managers.

If you have any questions regarding this matter, do not hesitate to call me.

Sincerely

Original signed by James M. Taylor

James M. Taylor Executive Director for Operations

Docket Nos. 50-237: 50-249

cc: See next page

<u>DISTRIBUTION:</u> See attached page

DOCUMENT NAME: G:\SECY2\DRES196.LTR

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy \*see previous page for concurrence

OFFICE	Reg Admin:RIII	DD:NRR	D:NRR	EDO X
NAME	HJMiller	FJMiraglia*	WTRussell*	JMTay/lor
DATE	/ /96	01/23/96	01/23/96	1/2m /96

OFFICIAL RECORD COPY

J. J. O'Connor Commonwealth Edison Company Dresden Nuclear Power Station Unit Nos. 2 and 3

## cc:

Michael I. Miller, Esquire Sidley and Austin One First National Plaza Chicago, Illinois 60603

Site Vice President Dresden Nuclear Power Station 6500 North Dresden Road Morris, Illinois 60450-9765

Station Manager Dresden Nuclear Power Station 6500 North Dresden Road Morris, Illinois 60450-9765

U.S. Nuclear Regulatory Commission Resident Inspectors Office Dresden Station 6500 North Dresden Road Morris, Illinois 60450-9766

Regional Administrator U.S. NRC, Region III 801 Warrenville Road Lisle, Illinois 60532-4351

Illinois Department of Nuclear Safety Office of Nuclear Facility Safety 1035 Outer Park Drive Springfield, Illinois 62704

Chairman Grundy County Board Administration Building 1320 Union Street Morris, Illinois 60450

Document Control Desk-Licensing Commonwealth Edison Company 1400 Opus Place, Suite 400 Downers Grove, Illinois 60515 DISTRIBUTION: for letter to James J. O'Connor (COMED)

Central Files
Public Document Room
EDO R.F., 0-17 G21
PIPB R.F., 0-12 E4
SECY, 0-16 G15
OPA, 0-2 G5
OCA, 0-17 F2
JLMilhoan, 0-17 G21
VMcCree, 0-17 G21
JLieberman, 0-7 H5
DLMorrison, T-10 F12
ELJordan, T-4 D18
ACThadani, 0-12 G18
RPZimmerman, 0-12 G18
RPZimmerman, 0-12 G18
RPZimmerman, 0-12 G18
RWBorchardt, 0-12 E4
GMTracy, 0-12 E4
PICastleman, 0-12 E4
WLAxelson, RIII
JWRoe, 0-13 E4
EGAdensam, 0-13 D1
JFStang, 0-13 D1