

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



May 14, 1996

JSPLTR #96-0073

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Licensee Event Report 95-018, Supplement 1, Docket 50-237 is being submitted pursuant to 10CFR50.73(a)(2)(i), which requires the reporting of any operation or condition prohibited by the Plant's Technical Specifications. This LER is also submitted pursuant to 10CFR50.73(a)(2)(ii) which requires reporting any event or condition that resulted in the condition of the nuclear power plant, including its principal safety barriers, being seriously degraded.


The LER supplement contains the root cause and corrective actions for the event.

This correspondence contains the following commitment:

1. The double gasket seal for the number 8 Shear Lug Inspection Hatch Cover will be repaired (2371809501803S1).

If you have any questions, please contact Pete Holland, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,


J. Stephen Perry
Site Vice President
Dresden Station

Enclosure

cc: H. Miller, Regional Administrator, Region III
NRC Resident Inspector's Office
Illinois Department of Nuclear Safety

200031

9605200154 960514
PDR ADOCK 05000237
S PDR

Handwritten initials/signature