Commonwealth Edison (Dresden Generating Station) 6500 North Dresden Road Morgis, IL 60450 Tel 815-942-2920

The incorrect dignee of 0.015 was the result of an error mude by the individual performing it a enformation. The operated unswellability of the Unit 2 Kigh Processor Control individual from any 1995 were fixed notionally interest. Mile resulted in the case **Control individual** control in the fixed notionally interest. Mile resulted in the case **Control individual**

Thuể 13' 1860 ^{thu} thể của nơi riệng đường presented to Christian Arceron. Như vềnh và thuất tổ là chun thể thiệng đường presented to Christian Arceron.

JSPLTR. #96-0093

50-237

U.S. Nuclear Regulatory Commission Document Control Desk Washington, D. C. 20555

The presentation made to Chairman Jackson in early May which supplied the April 30 goal results had an error in the <u>Unit 2</u> High Pressure Systems Unavailability Ratio twelve month rolling average. The goal for this area was 0.017. A figure of 0.015 was presented. The correct value is 0.021. The remaining Safety System unavailability numbers were recalculated and verified and found to be correct as they were presented to Chairman Jackson.

The incorrect figure of 0.015 was the result of an error made by the individual performing the calculation. The planned unavailability of the Unit 2 High Pressure Coolant Injection system for June 1995 was inadvertently missed. This resulted in the change identified above. The error was discovered when the figure was calculated for May 1996.

Sincerely,

VStephen Perry

Site Vice President Dresden Station

cc: H. Miller, Regional Administrator, Region III NRC Resident Inspector's Office Illinois Department of Nuclear Safety

200013

ADDCK

A Unicom Company

606190