

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



September 20, 1996

JSPLTR #96-0165

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555


Enclosed is Licensee Event Report 96-011, Docket 50-249 which is being submitted pursuant to 10 CFR 50.73(a)(2)(iv), which requires the reporting of any event or condition which results in manual or automatic actuation of any Engineered Safety Feature (ESF).

This correspondence contains the following commitments:

1. The Shift Manager of the Operations team involved will be responsible for creating and implementing an action plan to correct his teams communications problems. The action plan will be developed and actions pursued to completion. (2371809601101)
2. A Self-Assessment of the effectiveness of corrective action 2371809601101 will be performed. (2371809601102)
3. The Out of Service Procedure, DAP 3-5 will be revised to incorporate appropriate precautionary actions for consideration when returning equipment to service that has the potential for causing spurious Engineered Safety Feature actuations. (2371809601103)

If you have any questions, please contact Pete Holland, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,


J. Stephen Perry
Site Vice President
Dresden Station

Enclosure

cc: A. W. Beach, Regional Administrator, Region III
NRC Resident Inspector's Office
Illinois Department of Nuclear Safety

9609250005 960920
PDR ADOCK 05000249
S PDR

A Unicom Company

1/1
I e 22