

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



November 6, 1996

JSPLTR #96-0209

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555


Enclosed is Licensee Event Report 96-017, Docket 50-237, which is being submitted pursuant to 10CFR50.73 (a)(2)(v)(d) which requires that the licensee report any event or condition that alone could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident.

This correspondence contains the following commitments:

1. Restore the operability of the Control Room emergency zone boundary and Heating, Ventilation, and Cooling (HVAC) system by identifying and sealing leakage into the Control Room emergency zone until the differential pressure and in-leakage limitations can be met or initiate a licensing basis change request. (2371809601701)
2. The results of the root cause investigation and any significant corrective actions will be reported in a supplement to this LER. This root cause will address previous occurrences and the effectiveness of their corrective actions. (2371809601702)

If you have any questions, please contact Pete Holland, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,


J. Stephen Perry
Site Vice President

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office
Illinois Department Of Nuclear Safety

9611140279 961106
PDR ADOCK 05000237
S PDR

11
Ie22