

Commonwealth Edison Company  
Dresden Generating Station  
6500 North Dresden Road  
Morris, IL 60450  
Tel 815-942-2920



February 25, 1997

JSPLTR #97-0040

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Enclosed is Licensee Event Report 97-003, Docket 50-237, which is being submitted pursuant to 10 CFR 50.73(a)(2)(ii)(B) which requires the reporting of any event or condition that resulted in the nuclear power plant: In a condition that was outside the design basis of the plant.

This correspondence contains the following commitments:

1. To provide permanent corrective action, either over-pressure protection will be installed or penetration specific analytical considerations that confirm over pressurization is not a concern will be generated. The recommended corrective actions will be reported in a supplement to this LER. (NTS #2371809700301)
2. The modification process will be evaluated to ensure that future modifications account for overpressurization concerns. (NTS #2371809700302)
3. To ensure that appropriate lines are drained following future outages, procedures will be evaluated and changes made as necessary. (NTS #2371809700303)
4. Evaluate LLRT program and make changes as required to ensure that if existing credited valve leakage is corrected it is factored into the acceptance analysis. (NTS #2371809700304)

050032

9703050167 970225  
PDR ADQCK 05000237  
S PDR




USNRC  
February 25, 1997

Page 2

If you have any questions, please contact Pete Holland, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,

  
J. Stephen Perry  
Site Vice President  
Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III  
NRC Resident Inspector's Office