

Commonwealth Edison Company  
Dresden Generating Station  
6500 North Dresden Road  
Morris, IL 60450  
Tel 815-942-2920



August 29, 1997

JSPLTR #97-0151


U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

The enclosed supplement 1 to Licensee Event Report (LER) 95-001, Docket 50-237 is submitted in accordance with 10CFR50.73(a)(2)(v), which requires the reporting of any condition that alone could have prevented the fulfillment of the safety function of structures or systems needed to mitigate the consequences of an accident. The supplement is provided to update the safety evaluation and the corrective actions as a result of additional information revealed during the preparation of LER 96-017 Docket 50-237. Control Room Ventilation System Found Outside Design Limits Due to Unsealed Control Room Penetrations and Breaches Caused By Management and Modification Process Deficiencies.

This correspondence contains no additional commitments.

If you have any questions, please contact Terry Riley, Dresden Regulatory Assurance Supervisor at (815) 942-2920 extension, 2714.

Sincerely,

  
J. Stephen Perry  
Site Vice President  
Dresden Station

1/1  
Terry

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III  
NRC Resident Inspector's Office

9709040353 970829  
PDR ADOCK 05000237  
S PDR

