

Commonwealth Edison Company  
Dresden Generating Station  
6500 North Dresden Road  
Morris, IL 60450  
Tel 815-942-2920



January 21, 1998

JMHLTR #98-0022

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555


Enclosed is Licensee Event Report 97-018, Docket 50-237, which is being submitted pursuant to 10 CFR 50.73(a)(2)(iv) which requires the reporting of any event or condition that results in a manual or automatic actuation of any Engineered Safety Feature.

This correspondence contains the following commitment:

The initial investigation did not identify the root cause of the High Pressure Coolant Injection Isolation. However, two relays were suspected to have contributed to this event. These relays were replaced and the removed relays were scheduled for further evaluation. Upon completion of the failure analysis of these relays, a supplemental report will be submitted. (237-180-97-01801)

If you have any questions, please contact Frank Spangenberg, Dresden Regulatory Assurance Manager at (815) 942-2920 extension, 3800.

Sincerely,

  
J. M. Heffley  
Site Vice President  
Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III  
NRC Resident Inspector's Office

9801270100 980121  
PDR ADOCK 05000237  
S PDR

1/22

