

DR Control file



50-237

Telegram

DEB840 SSA136

1971 DEC 30 AM 9 35

DE JLA006 ZO PD=TDJL MORRIS ILL 30 835A CST=
 BOYCE GRIER US ATOMIC ENERGY COMMISSION=
 REGION 3 COMPLIANCE 799 ROOSEVELT RD GLEN ELLYN ILL=
 DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2: THIS WILL
 CONFIRM A CONVERSATION AT 14:15 HOURS THIS DATE WITH H
 DANCE REGARDING THE FAILURE OF A MAIN STEAM LINE FLOW
 SWITCH WHICH WAS DISCOVERED DURING ROUTINE SURVEILLANCE
 ON 12/29/71 AT 11:00 HOURS. MOISTURE LEAKED INTO A JUNCTION
 BOX AND TRAVELLED THROUGH A CONDUIT INTO THE SWITCH. THIS
 CAUSED THE SWITCH TO BE IMMOBILIZED BY RUST. THE ISOLATION
 CHANNEL WHICH WAS OPERATED BY THE SWITCH WAS PUT IN THE

WU 1201 (R. 5-69)

TRIP CONDITION DURING THE REPAIRS. THE SWITCH WAS
 REPLACED AND THE JUNCTION BOX WAS SEALED AGAINST MOISTURE=
 H K HOYT SUPT DRESDEN NUCLEAR POWER STATION
 MORRIS ILL.=

TELEPHONE NO. 858-2660
 TELEPHONE TO Bea
 TIME DELIVERED 945
 BY W TO BE Med

DPR-19 2 14:15 12/29/71 11:00

1 5404
1408

WU 1201 (R. 5-69)

Dupe

med