

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920



May 20, 1998

JMHLTR: #98-0151

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555


Enclosed is Licensee Event Report 98-008, Docket 50-237, which describes an automatic reactor scram due to a Main Turbine/Generator trip. This LER is being submitted as an interim report pursuant to 10 CFR 50.73(a)(2)(iv), which requires the reporting of any event or condition that results in manual or automatic actuation of any Engineered Safety Feature (ESF), including the Reactor Protection System (RPS). A supplemental report is scheduled to be submitted following the conclusion of our investigation.

This correspondence contains the following commitment:

The same relay modification (M12-2-96-004) has been issued for the Reserve Auxiliary Transformer (RAT) T22. The RAT modification has not been installed at this time (scheduled for D2R16). A formal documented review will be performed to verify that the CT connections are correctly wired for the RAT modification. (NTS 2371809800801)

If you have any questions, please contact Frank Spangenberg, Dresden Regulatory Assurance Manager at (815) 942-2920 extension, 3800.

Sincerely,


J. M. Heffley
Site Vice President
Dresden Station

Enclosure

cc: A. Bill Beach, Regional Administrator, Region III
NRC Resident Inspector's Office

9805280151 980520
PDR ADOCK 05000237
S PDR

Handwritten notes: 3622