

Commonwealth Edison Company
Dresden Generating Station
6500 North Dresden Road
Morris, IL 60450
Tel 815-942-2920

ComEd

June 3, 1998

JMHLTR: #98-0161

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Enclosed is Licensee Event Report 98-009, Docket 50-237, which describes the inoperability of the High Pressure Coolant Injection System. This condition is being reported as an interim report pursuant to 10 CFR 50.73(a)(2)(v)(D) which requires the reporting of any event or condition that alone could have prevented the fulfillment of the safety function of a system required to mitigate the consequences of an accident. A supplemental report is scheduled to be submitted following the conclusion of our investigation.

The following actions were taken:


1. The Unit 2 HPCI GSLO hotwell pump start/stop level switches were replaced with specially selected new switches provided by the Original Equipment Manufacturer (OEM) and were satisfactorily tested. (Complete)
2. The Unit 3 HPCI GSLO hotwell pump start/stop level switches were replaced with the specially selected new switches provided by the OEM and were satisfactorily tested. (Complete)
3. The parts requisition system was updated to use the new OEM part number for the switches enhanced with stronger magnets and float stops. (Complete)

This correspondence contains the following commitment:

1. A supplemental LER will be provided to the NRC with the finalized root cause, any additional significant corrective actions and any previous occurrences. (NTS 237-180-98-00902)

If you have any questions, please contact Frank Spangenberg, Dresden Regulatory Assurance Manager at (815) 942-2920 extension, 3800.

Sincerely,


J. M. Henley
Site Vice President
Dresden Station

Enclosure

030034

cc: Carl Paperiello, Acting Regional Administrator, Region III
NRC Resident Inspector's Office

9806100258 980603
PDR ADOCK 05000237
S PDR

A Unicom Company

11
IE22