

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	I	L	D	R	S	2	2	0	0	-	0	0	0	0	0	0	0	3	4	1	1	1	1	4		5																										
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34																										
CON'T		REPORT SOURCE		L		6		0		5		0		0		2		3		7		7		0		9		1		1		8		0		8		1		0		0		5		8		0		9			
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0	2	During a recent Quality Assurance Audit, it was discovered that the Control Room and																																																					
0	3	Computer Room smoke detectors were out of service for longer than 14 days and the																																																					
0	4	Commission was not notified as to the plans for restoring these smoke detectors to an																																																					
0	5	operable status. This event was of minimal safety significance since these areas are																																																					
0	6	normally occupied and the personnel there would have been able to take necessary action																																																					
0	7	in the event of a fire. First event of this type at Dresden.																																																					

0	9	SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP. SUBCODE		VALVE SUBCODE		LER/RO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.	
7	8	A B		A		B		Z Z Z Z Z Z Z		Z		Z		8 0		0 3 5		0 3		L		0			
9	10	11		12		13		14		15		16		17		18		19		20		21		22	
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER									
X		Z		Z		Z		0 0 0 0		N		N		Z		Z 9 9 9									
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50								

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1	0	The smoke detectors were removed in order to install a modification to provide an																																																					
1	1	upgraded system of smoke detectors. Tech. Spec. Requirement 3.12.A.2.b. was overlooked																																																					
1	2	by the Station Fire Marshal. The modification was completed in September of 1980 and																																																					
1	3	the new smoke detectors were functionally tested before being returned to service. No																																																					
1	4	further action is required.																																																					

1	5	FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
7	8	E		0 6 1		N/A		C		Quality Assurance Audit	
9	10	28		29		30		31		32	
ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE					
Z		Z		N/A		N/A					
7	8	33		34		35		36			
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION					
0 0 0		37		Z		N/A					
7	8	38		39		40		41			
PERSONNEL INJURIES		NUMBER		DESCRIPTION							
0 0 0		40		N/A							
7	8	41		42		43		44			
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION							
Z		42		N/A							
7	8	43		44		45		46			
PUBLCITY		ISSUED		DESCRIPTION							
2 0		N		N/A							
7	8	44		45		46		47			

NAME OF PREPARER M. Korchynsky

PHONE: X-523

8010150515

NRC USE ONLY