



ATTACHMENT TO LICENSEE EVENT REPORT 81-06/01T-0  
COMMONWEALTH EDISON COMPANY (CWE)  
DRESDEN UNIT 2 (ILDRS-2)  
DOCKET #050-237

During Unit 2 refueling outage, LLRT performed on the feedwater check valves measured leakages in excess of that allowed by: (1) a single penetration (29.38 SCFH), (2) total penetration and isolation valve leakage (176.29 SCFH) and (3) total containment leakage of 783 SCFH, per tech Spec 4.7.A. This was of minimal safety significance since the feedwater line is capable of being isolated by a motor operated valve upstream of the check valves. Similar event: 50-237/80-06.

The feedwater check valves have not been repaired as of this date. A supplemental report will be sent when all repairs and corrective actions have been completed.