



**Commonwealth Edison**  
 One First National Plaza, Chicago, Illinois  
 Address Reply to: Post Office Box 767  
 Chicago, Illinois 60690

*Central  
Files*

January 23, 1981

Mr. James G. Keppler, Director  
 Directorate of Inspection and  
 Enforcement - Region III  
 U.S. Nuclear Regulatory Commission  
 799 Roosevelt Road  
 Glen Ellyn, IL 60137

Subject: Dresden Station Unit 2  
 Response to IE Bulletin 80-13  
 "Cracking in Core Spray Spargers"  
NRC Docket No. 50-237

Reference (a): J. G. Keppler letter to C. Reed dated  
 May 12, 1980

Dear Mr. Keppler:

Reference (a) transmitted IE Bulletin 80-13, which  
 identified instances of cracking in Core Spray Spargers at BWR  
 facilities.

As required by Bulletin item 1, the Dresden Unit 2 Core  
 Spray Spargers were visually inspected on January 15, 1981,  
 utilizing a remote underwater TV Camera. All accessible portions of  
 both the upper and lower spargers and the segment of piping between  
 the inlet nozzle and vessel shroud were examined. A wire template  
 was used to insure adequate resolution.

No adverse conditions or abnormalities were observed during  
 the inspection.

Please address any questions you may have concerning this  
 matter to this office.


Very truly yours,

*Thomas J. Rausch*  
 Thomas J. Rausch  
 Nuclear Licensing Administrator  
 Special Projects

cc: NRC Office of Inspection  
 and Enforcement

NRC RIII Inspector - Dresden

0019B



JAN 26 1981

8102120548

Q