



1974 FEB 13 PM 8:40

VEB377(2118)(1-047431C044)PD 02/13/74 2116

ICS IPMVEIB MVN

02328 TDVE MORRIS IL 102 02-13 346P CDT

PMS MR JAMES G KEPPLER

REGIONAL DIRECTOR

DIRECTORATE OF REGULATORY OPERATIONS

REGION 3

US ATOMIC ENERGY COMMISSION

799 ROOSEVELT RD

GLENELLYN IL 60137

TELEGRAM (OTHER THAN MONEY ORDERS)

312-858-2660

1030 A 12 - BY
mail

SUBJECT DPR-19 DRESDEN NUCLEAR POWER STATION UNIT 2.

THIS WILL CONFIRM A CONVERSATION WITH F. NAURA OF YOUR OFFICE

AT 1030 HOURS THIS DATE CONCERNING INSPECTION OF BERGEN-

PATTERSON HYDRAULIC ^{FRM} PIPING RESTRAINT WITHIN THE DRY WELL

DURING THE CURRENT PLANT OUTAGE. AS NOTIFIED TO YOU

ON 2-11-74. DURING THIS INSPECTION 12 OF THE 31

SF-1201 (RS-69)



1974 FEB 13 PM 8:40

RESTRAINTS WITHIN THE DRY WELL WERE FOUND TO BE DEFECTIVE

DUE TO THE LOSS OF HYDRAULIC FLUID. A PROGRAM IS BEING

INITIATED TO OVERHAUL THESE 12 RESTRAINTS AND WILL BE

RECORDED TO YOU IN A FOLLOWING 10-DAY NOTIFICATION.

W.P.WORDEN SUPERINTENDENT DRESDEN NUCLEAR POWER STATION

COMMONWEALTH EDISON COMPANY RURAL ROUTE 1 MORRIS IL

NNNN

1301 74

FEB 19 1974

8103030307

SF-1201 (RS-69)