


TWX INCOMING

BETH  
008

50-237

Regulatory Docket File



USAEC GTWN


WU INFOMASTER 1-038010C028 01/28/75  
TLX WU TFC WSH  
098  
TWX 7108280476 USAEC GTWN

SPL098 WAB170(1745)(2-034177E028)PD 01/28/75 1745  
ICS IPMBNGZ CSP  
8159424449 TDBN MORRIS IL 85 01-28 0545P EST  
PMS J F OLEARY, DIRECTOR, DIRECTORATE OF LICENSING, US ATOMIC  
~~ENERGY COMMISSION~~, WUX  
WASHINGTON DC 20545

SUBJECT: DPR-19, DRESDEN NUCLEAR POWER STATION UNIT 2.  
THIS WILL CONFIRM A CONVERSATION WITH MR JOHNSON OF YOUR OFFICE  
AT 0930 HOURS THIS DATE CONCERNING CRACKS FOUND OF CORE SPRAY  
INJECTION LINES IN AREA OF LINE BETWEEN SAFE END AND INJECTION  
LINE. CRACK THROUGH THE WALL WERE FOUND AT 8:00, 3 OCLOCK AND  
12 OCLOCK IN N19A NOVEL AREA, AND AT 10 AND 1130 ON THE N19B  
NOVEL AREA. INVESTIGATION INTO CAUSE OF FAILURE IS UNDER WAY  
B B STEPHENSON, SUPERINTENDENT, DRESDEN NUCLEAR POWER STATION,  
COMMONWEALTH EDISON CO, RRI MORRIS IL 60450

1904 EST

USAEC GTWN



976

TWX INCOMING

8103060534