



Commonwealth Edison
 Dresden Nuclear Power Station
 R.R. #1
 Morris, Illinois 60450
 Telephone 815/942-2920

DSB

February 19, 1981


DJS LTR #81-157

James G. Keppler, Regional Director
 Directorate of Regulatory Operations - Region III
 U.S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, IL 60137

Reportable Occurrence Report #81-04/03X-1, Docket #050-249 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.2.(c), observed inadequacies in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems. This revision corrects our transmittal letter dated January 28, 1981. The Reportable Occurrence Report #81-03/03L-0 and Docket #050-237 numbers were incorrect.

D. V. Scott

D. V. Scott
 Station Superintendent
 Dresden Nuclear Power Station



DJS/lg

Enclosure

cc: Director of Inspection & Enforcement
 Director of Management Information & Program Control
 U.S. NRC, Document Mgt. Branch
 File/NRC

*A002
 S
 1/1*

MAR 5 1981

8103090549

SUPPLEMENT TO DVR

DVR NO.	STA	UNIT.	YEAR	NO.
D - 12	- 3	- 81	- 8	

PART 1	TITLE OF EVENT	OCCURRED
	Unit 3 EHC Low Oil Pressure Scram Surveillance Interval Exceeded	1/2/81 15:10 DATE TIME
REASON FOR SUPPLEMENTAL REPORT		
The Reportable Occurrence Report #81-03/03L-0 and Docket #050-237 numbers were incorrect as indicated by our transmittal letter dated January 28, 1981. The correct Reportable Occurrence Report number and docket are 81-04/03L-0 and 050-249 respectively.		
PART 2		
ACCEPTANCE BY STATION REVIEW	<u>J Brunner</u> <u>Michael Wright</u>	
DATE	<u>3/2/81</u> <u>3-2-81</u>	
SUPPLEMENTAL REPORT APPROVED AND AUTHORIZED FOR DISTRIBUTION	<u>Douglas Scott</u> STATION SUPERINTENDENT	<u>3/2/81</u> DATE