

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: I L D R S 3 0 0 - 0 0 0 0 0 - 0 0 4 1 1 1 1 LICENSE NUMBER: 25 26 LICENSE TYPE: 30 57 CAT 58

REPORT SOURCE: L 0 5 0 0 0 2 4 9 0 1 0 2 8 1 0 2 1 9 8 1 DOCKET NUMBER: 68 69 EVENT DATE: 74 75 REPORT DATE: 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

During steady state operation on 2 January 81, it was determined that a surveillance that was to be performed no later than 1 January, 81, was not performed. The procedure (DIS 500-8, EHC Low Oil Pressure Scram) is required to be performed by Table 4.1.1 of the Tech. Specs. and the frequency interval exceeded that defined in the Tech. Specs. There was no effect on the public health or safety. Similar occurrence: R. O. #79-049/03I-0.

SYSTEM CODE: Z Z CAUSE CODE: A CAUSE SUBCODE: C COMPONENT CODE: I N S T R U COMP. SUBCODE: X VALVE SUBCODE: Z LER/RO REPORT NUMBER: 8 1 EVENT YEAR: 8 1 SEQUENTIAL REPORT NO.: 0 0 4 OCCURRENCE CODE: 0 3 REPORT TYPE: X REVISION NO.: 1 ACTION TAKEN: E FUTURE ACTION: Z EFFECT ON PLANT: Z SHUTDOWN METHOD: Z HOURS: 0 0 0 0 ATTACHMENT SUBMITTED: N NPRD-4 FORM SUB.: N PRIME COMP. SUPPLIER: Z COMPONENT MANUFACTURER: Z 9 9 9

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

The cause was due to personnel error by failing to account for the New Years Day holiday when scheduling surveillance. The surveillance was performed on the day of discovery. The cause of the occurrence was reviewed with all personnel involved. No further corrective action necessary.

FACILITY STATUS: E % POWER: 0 6 8 OTHER STATUS: N/A METHOD OF DISCOVERY: A DISCOVERY DESCRIPTION: Observation

ACTIVITY CONTENT RELEASED OF RELEASE: Z AMOUNT OF ACTIVITY: N/A LOCATION OF RELEASE: N/A

PERSONNEL EXPOSURES NUMBER: 0 0 0 TYPE: Z DESCRIPTION: N/A

PERSONNEL INJURIES NUMBER: 0 0 0 DESCRIPTION: N/A

LOSS OF OR DAMAGE TO FACILITY TYPE: Z DESCRIPTION: N/A

PUBLICITY ISSUED DESCRIPTION: N

NAME OF PREPARER: W. E. McGee PHONE: 815-942-2920 Ext. 465

8103090 552