

LICENSEE EVENT REPORT

PREVIOUS REPORT DATE: 6/23/77

CONTROL BLOCK: 1 6

PLEASE PRINT ALL REQUIRED INFORMATION

LICENSEE NAME 01 I L D R S 2 7 8 9 14							LICENSE NUMBER 00-000000-00 15 25										LICENSE TYPE 41111 26 30				EVENT TYPE 03 31 32	
CATEGORY 01 CONT 7 8		REPORT TYPE L 57 58		REPORT SOURCE L 59 60		DOCKET NUMBER 050-0237 61 68					EVENT DATE 052776 69 74				REPORT DATE 070676 75 80							

EVENT DESCRIPTION

02 DURING ROUTINE SURVEILLANCE TESTING, REACTOR PROTECTION SYSTEM 600 PSI BYPASS PRESSURE SWITCH PS 2-263-51A WAS FOUND TO ACTUATE AT 600 PSI (TECH SPEC LIMIT: LESS THAN 600PSI) SYSTEM OPERABILITY WAS NOT AFFECTED BECAUSE REDUNDANT PRESSURE SWITCH 2-263-51B OPERATED PROPERLY. PS 2-263-51A WAS ADJUSTED TO THE PROPER SETPOINT. REPORTABLE SETPOINT DRIFT ON SIMILAR SWITCHES HAS OCCURRED SEVERAL TIMES. (50-237/1976-37)

SYSTEM CODE 07 I A 7 8 9 10		CAUSE CODE E 11		COMPONENT CODE I N S T R U 12 17				PRIME COMPONENT SUPPLIER N 43		COMPONENT MANUFACTURER M 2 2 5 44 47			VIOLATION Y 48	
-----------------------------------	--	-----------------------	--	--	--	--	--	-------------------------------------	--	--	--	--	----------------------	--

CAUSE DESCRIPTION

08 THE EVENT WAS CAUSED BY INSTRUMENT SETPOINT DRIFT. PS 2-263-51A WILL BE INSPECTED ON A MONTHLY BASIS UNTIL IT CONSISTENTLY EXHIBITS WHAT THE STATION CONSIDERS TO BE ACCEPTABLY CONSERVATIVE DRIFT.

FACILITY STATUS 11 C 7 8 9		% POWER 025 10 12 13			OTHER STATUS NA 44			METHOD OF DISCOVERY B 45		DISCOVERY DESCRIPTION NA 46 80			
----------------------------------	--	----------------------------	--	--	--------------------------	--	--	--------------------------------	--	--------------------------------------	--	--	--

FORM OF ACTIVITY RELEASED 12 Z 7 8 9		CONTENT OF RELEASE Z 10		AMOUNT OF ACTIVITY NA 11 44				LOCATION OF RELEASE NA 45 80			
--	--	-------------------------------	--	-----------------------------------	--	--	--	------------------------------------	--	--	--

PERSONNEL EXPOSURES

NUMBER 13 000 7 8 9 11			TYPE Z 12		DESCRIPTION NA 13 80			
------------------------------	--	--	-----------------	--	----------------------------	--	--	--

PERSONNEL INJURIES

NUMBER 14 000 7 8 9 11			DESCRIPTION NA 12 80			
------------------------------	--	--	----------------------------	--	--	--

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE 16 Z 7 8 9 10		DESCRIPTION NA 80					
--------------------------	--	-------------------------	--	--	--	--	--

PUBLICITY

17 NA

ADDITIONAL FACTORS

18

19

NAME: G. REIMERS 8103100052 PHONE: EXT. 265



**Commonwealth Edison**

Dresden Nuclear Power Station

R.R. #1


Morris, Illinois 60450

Telephone 815/942-2920

BBS Ltr. #76-511

July 6, 1976

Mr. James G. Keppler, Regional Director  
Directorate of Regulatory Operations - Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137



Enclosed please find an update report to Reportable Occurrence Report number 50-237/1976-37. This report is being submitted to your office in accordance with the Dresden Nuclear Power Station Technical Specifications, Section 6.6.B.


B. B. Stephenson  
Station Superintendent  
Dresden Nuclear Power Station

BBS:jo

Enclosure

cc: Director of Inspection & Enforcement  
Director of Management Information & Program Control  
File/NRC

7047



Regulatory Docket File