

WESTERN UNION INCOMING

DOCKET NO. 50-237

Butler
008

Regulatory Docket File

1973 AUG 16 PM 4 40

USAEC HQS GTWN

U.S. ATOMIC ENERGY COMM.
T W X UNIT

WU WSH

LXA129 WAF340(1438)(1-020294C228)PD 08/16/73 1425

ICS IPMVEIA MVN

01180 TDVE MORRIS IL 84-5EX 08-16 1P CDT

PMS MR A GIAMBUSSO

DEPUTY DIRECTOR FOR REACTOR PROJECT


DIRECTORATE OF LICENSING

USA ATOMIC ENERGY COMMISSION

WUX

WASHINGTON DC 20545

SUBJECT: DPR-19 DRESDEN NUCLEAR POWER STATION NO 2




THIS WILL CONFIRM A CONVERSATION WITH MR. FRED MAURA OF YOUR OFFICE AT 1145 HOURS THIS DATE CONCERNING A FAILURE OF THE HIGH PRESSURE COOLANT

INJECTION SYSTEM STEAM SUPPLY VALVE. M02-2301-3 WHILE CONDUCTING MONTHLY VALVE AND PUMP SURVEILLANCE THE VALVE FAILED IN THE MID POSITION RENDERING THE HPCI SYSTEM INOPERABLE. THE REQUIRED SURVEILLANCE

FOR AN INOPERABLE HPCI SYSTEM WAS CONDUCTED AND AN INSPECTION OF THE FAILED VALVE HAS COMMENCEDM W.P. WORDEN

SUPERINTENDENT DRESDEN NUCLEAR POWER STATION COMMONWEALTH EDISON COMPANY ROUTE 1 MORRIS IL.



436P EDT AUG QY 73+

USAEC HQS GTWN

177.4

6290

WU WSH

8103130345