




Commonwealth Edison
 Dresden Nuclear Power Station
 R.R. #1
 Morris, Illinois 60450
 Telephone 815/942-2920

DLB

March 9, 1981

DJS LTR #81-167



James G. Keppler, Regional Director
 Directorate of Regulatory Operations - Region III
 U.S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, IL 60137

Reportable Occurrence Report #81-10/01T-0, Docket #050-237 is being submitted to your office in accordance with Dresden Nuclear Power Station Technical Specification 6.6.B.1 (i). Performance of structures, systems, or components that requires remedial action or corrective measures to prevent operation in a manner less conservative than assumed in the accident analyses in the safety analysis report or technical specifications bases; or discovery during plant life of conditions not specifically considered in the safety analysis report or technical specifications that require remedial action or corrective measures to prevent the existence or development of an unsafe condition.

This report combines two separate occurrences as indicated by the attached DVR Numbers 12-2-81-17 and 12-2-81-22. The result of combining these events is that the first event is being reported more than 14 days after it occurred. An agreement was reached with the Senior Resident Inspector, T. Tongue, that a seven day extension would be allowed on the first report so that both occurrences could be combined into one License Event Report.

DJ Scott

D. J. Scott
 Station Superintendent
 Dresden Nuclear Power Station

*A002
 S
 1/1*

DJS:lg

Enclosure

cc: Director of Inspection & Enforcement
 Director of Management Information & Program Control
 U. S. NRC, Document Mgt. Branch
 File/NRC

5

8108170543

MAR 11 1981