

TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

June 19, 1980

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

**HARTSVILLE AND PHIPPS BEND NUCLEAR PLANTS - REPORTABLE DEFICIENCY -
INCORRECT ROOT FACE ON SKEWED CADWELD SLEEVES (NCR'S HTH CEB 80-04,
PBN CEB 80-04; FORMERLY NCR CEB 80-11)**

Initial notification of the subject deficiency was made to NRC-OIE,
Region II, Inspector R. W. Wright on March 14, 1980. The first
interim report of this deficiency, formerly NCR CEB 80-11, was submitted
on April 14, 1980. In compliance with paragraph 50.55(e) of 10 CFR
Part 50, we are enclosing the final report of the subject deficiency.
If you have any questions regarding this subject, please call Jim Domez
at FIS 857-2014.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

L. M. Mills, Manager
Nuclear Regulation and Safety

Enclosure

cc: Mr. Victor Stallo, Director (Enclosure) ✓
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, DC 20555

POOR ORIGINAL

Boig 3/11

8006250275