



Commonwealth Edison

One First National Plaza, Chicago, Illinois

Address Reply to: Post Office Box 767

Chicago, Illinois 60690

March 30, 1989

Dr. Thomas E. Murley, Director
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, DC 20555

Subject: Dresden Nuclear Power Station Unit 2
Final Report on the Fall 1988
Inspection of Stainless Steel Piping
NRC Docket Nos. 50-237

Reference: Letter from J.A. Silady to T.E. Murley dated
February 6, 1989

Dear Dr. Murley:

In the referenced letter, Commonwealth Edison reported the Intergranular Stress Corrosion Cracking (IGSCC) flaws identified and the analytical and repair actions taken during the Dresden Unit 2 Fall 1988 Eleventh Refueling (D2R11) outage. The purpose of this letter is to transmit the following document.

"Structural Integrity Associates, Inc., Report No. SIR-89-004, Volume 2, Revision 0, "Dresden Nuclear Power Station Unit 2, Flaw Evaluation and Repair Design Report, Fall 1988 Refueling Outage."

This volume of the report covers the as-built reconciliation of the weld overlay repair and weld overlay examinations performed during the Fall 1988 refueling outage with the analyses and designs presented in Volume 1, which was previously submitted by the referenced letter.

This transmittal completes the reporting of analyses and weld overlay repair efforts for the D2R11 outage IGSCC Inspection Program per Generic Letter 88-01.

8904110163 890330
PDR ADOCK 05000237
Q PDC

A001
11/1

Please contact this office should further information be required.

Very truly yours,



J. A. Silady
Nuclear Licensing Administrator

lm

Attachment

cc: A.B. Davis - Regional Administrator, RIII
B.L. Siegel - Project Manger, NRR
S.G. DuPont - Senior Resident Inspector, Dresden

0058T