




**Commonwealth Edison**  
Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

June 28, 1990

EDE LTR #90-449

U.S. Nuclear Regulatory Commission  
Document Control Desk  
Washington, D.C. 20555

Attached please find Licensee Event Report #89-004-01. This revised report is submitted to correct an error identified by the Corporate Nuclear Safety Review Group involving the surveillance frequency for replacement of the High Pressure Coolant Injection (HPCI) system room cooler drive belts. The original report listed this as an annual frequency; however, the actual frequency is once per refuel outage. This revision also clarifies that lubrication of the HPCI room cooler bearings is currently a quarterly surveillance activity. Additionally, this revision provides an updated status of the corrective actions to prevent recurrence, reporting that a drive shaft/bearing assembly was replaced.

  
E.D. Eenigenburg  
Station Manager  
Dresden Nuclear Power Station

EDE/jt

Enclosure

cc: A. Bert Davis, Regional Administrator, Region III  
File/NRC  
File/Numerical

0909k

5007170314 900628  
FDR ADDCK 05000249  
S FDC

IE22  
11