

REGULATOR INFORMATION DISTRIBUTION SYSTEM

DOCKET NBR: 50-335 ST LUCIE 1
 RECIPIENT: O'REILLY, J.P.
 ORIGINATOR: SCHMIDT, A.D.
 COMPANY NAME: FLA PWR & LIGHT CO
 SUBJECT:

DOC DATE: 781127
 ACCESSION NBR: 7812050195
 COPIES RECEIVED:
 LTR 1 ENCL 1
 SIZE: 1+1

LER#78-035/03L-0 "Update" on 780905: 2 damper motors in suction line for HVE-9B
 blew fuses in control circuits. Original rept incorrect. Caused by fuses blown in
 control circuits for filter plenum inlet & outlet damper motors of B.

DISTRIBUTION CODE: A002
 DISTRIBUTION TITLE:
 INCIDENT REPORTS

NOTARIZED _____

NAME	ENCL?	FOR ACTION
BR CHIEF	W/4 ENCL	ORB#4 BC
REG FILE	W/ENCL	_____
NRC PDR	W/ENCL	_____
I & E	W/2 ENCL	_____
MIPC	W/3 ENCL	_____
I & C SYSTEMS BR	W/ENCL	
NOVAK/CHECK	W/ENCL	
EEB	W/ENCL	
AD FOR ENG	W/ENCL	
PLANT SYSTEMS BR	W/ENCL	
HANAUER	W/ENCL	
AD FOR PLANT SYSTEMS	W/ENCL	
AD FOR SYS & PROJ	W/ENCL	
REACTOR SAFETY BR	W/ENCL	
ENGINEERING BR	W/ENCL	
KREGER/J. COLLINS	W/ENCL	
POWER SYS BR	W/ENCL	
E. Jordan	W/ENCL	
LPDR	W/ENCL	
NSIC	W/ENCL	
ACRS	W/16 ENCL	

TOTAL NUMBER OF COPIES REQUIRED:

LTR 42
 ENCL 42

DEC 6 1978

NOTES:

AO 4
 60

DEC 2 1950



November 27, 1978

PRN-LI-78-345

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia. 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-78-35
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: SEPTEMBER 5, 1978

ECCS AREA FILTER TRAIN
UPDATE REPORT NO. 1

The attached Licensee Event Report is being submitted to update our initial report of September 27, 1978.

Very truly yours,

J.R. Bensen
for A. D. Schmidt
Vice President
Power Resources

MAS/cpc

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Director, Office of Management Information and Program Control (3)
Harold F. Reis, Esquire
File 933.1SL

REGULATORY DOCKET FILE COPY

7812050195

REGULATORY DOCKET FILE COPY