

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7906140376 DOC. DATE: 79/05/25 NOTARIZED: NO  
 FACIL: 50-335 St. Lucie Plant, Unit 1, Florida Power & Light Co.  
 AUTH. NAME: WETHY, C.M. AUTHOR AFFILIATION: Florida Power & Light Co.  
 RECIP. NAME: O'REILLY, J.P. RECIPIENT AFFILIATION: Region 2, Atlanta, Office of the Director

DOCKET # 05000335

SUBJECT: RO 335-79-16 on 790523: four restraints were misplaced on 4 inch & 8 inch component cooling water lines. Four restraints will be properly installed before startup from present refueling shutdown.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 4 ENCL 0 SIZE: / TITLE: INCIDENT REPORTS


NOTES: .....

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	05 BC ORB #4	4	4			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 KREGER	1	1	25 PWR SYS BR	1	1
	26 AD/SITE ANAL	1	1	27 OPERA LIC BR	1	1
	28 ACIDENT ANALY	1	1	29 AUX SYS BR	1	1
	E JORDAN/IE	1	1	HANAUER, S.	1	1
	TMI DOC CENTER	1	1			
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

JUN 15 1979

AO 4  
60

TOTAL NUMBER OF COPIES REQUIRED: LTR 48 ENCL 48



CHAS

POST OFFICE BOX 178 FT PALM BEACH FLORIDA 3

CMW/PSL  
Ltr. Bk # 557

Copies to: CMW, JHB, CAW, GIV, RRJ.

Offsite: ADS, JRB, COW, MAS, REU, KNH

To: Mr. J. P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Atlanta, Georgia 30303

From: Mr. C. M. Wethy, Plant Manager  
St. Lucia Plant - DPR 67  
Florida Power & Light Company  
Miami, Florida

FLORIDA POWER & LIGHT CO.  
May 25, 1979  
ESNRC REGION II  
ATLANTA, GEORGIA  
79 MAY 29 AIO: 35

Subject: MEMO FOR FACSIMILE TRANSMISSION TO CONFIRM PROMPT  
REPORTABLE OCCURRENCE 335-79-16

This memo confirms our verbal notification of the subject 14 day reportable occurrence to Mr. E. H. Webster of your office yesterday.

Occurrence: On May 23 at about 4 p.m., a report was received from Ebasco through our Engineering Department that a restraint problem had been noted while completing as built print verification in containment. Two restraints were interchanged on two 8" Component Cooling Water (CCW) lines running parallel about 2 feet apart. Two other restraints were mistakenly installed on 4" CCW piping of similar configuration but at a different azimuthal location. This portion of CCW is non-safety related but was designed to be seismically restrained due to an adjacent 1" fill line for a safety injection tank (accumulator). Assuming a seismic event and LOCA the 1" line, if ruptured, would have no significant effect on SIT operations and very little effect on the SI header it is attached to.

Corrective Action

The 4 misplaced restraints will be properly installed before startup from the present refueling shutdown.

REGULATORY DOCKET FILE COPY

- ~~B. P. O'REILLY~~
- ~~A. M. UPRIGHT~~
- ~~P. D. CHENDEME~~
- ~~W. E. KENNA~~
- ~~F. J. LONG~~
- ~~R. E. MURPHY~~
- ~~A. J. SUTHERLAND~~
- ~~R. M. CLARK~~
- Lewis*
- Pfeiffer*
- Webster*

A002  
5/10

7906140376

