

USNRC REGION II
ATLANTA, GEORGIA



79 AUG 2 A 8: 51

July 31, 1979
L-79-207

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, N. W., Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-389
IE Bulletin 79-11

Florida Power & Light Company has reviewed IE Bulletin 79-11 concerning problems encountered with Westinghouse DB-50 and DB-75 circuit breakers.

We have surveyed our safety related Class IE equipment and have determined that neither Westinghouse DB-50 nor DB-75 circuit breakers will be used in such equipment.

This completes our action in response to IE Bulletin 79-11.

Very truly yours,

A handwritten signature in cursive script that reads "Robert E. Uhrig".

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU:MV:cf

cc: Harold F. Reis, Esquire

A large handwritten checkmark or the letter "T" drawn with a single stroke.

AI/O
~~XXXXXXXXXX~~

7908220578

79098
OFFICIAL COPY