

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7910250374 DOC. DATE: 79/10/04 NOTARIZED: NO DOCKET # 05000389  
 FACIL: 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co.  
 AUTH. NAME: UHRIG, R.E. AUTHOR AFFILIATION: Florida Power & Light Co.  
 RECIP. NAME: O'REILLY, J.P. RECIPIENT AFFILIATION: Region 2, Atlanta, Office of the Director

SUBJECT: Forwards interim deficiency rept re damage of reactor auxiliary bldg & shield bldg resulting from derrick collapse on 790903 during Hurricane David.

DISTRIBUTION CODE: B019S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 16  
 TITLE: EI & C Drawings

NOTES: -----

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL		ID CODE/NAME	LTR
	14 PM BIRKEL	1		15 BC LWR# 2	1	
	20 LA LWR# 2	1		21 AD LWR	1	
INTERNAL:	01 REG FILE	1		02 NRC PDR	1	
	05 I&E	2		07 EDO & STAFF	1	
	08 MPA	1		09 DEPY DIR DPM	1	
	10 QAB	1		11 STANDRDS DEV	1	
	12 JORDAN, E/IE	1		13 FIELD COOR/IE	1	
	16 AD FOR ENGR	1		17 AD PLANT SYS	1	
	17 AD REAC SFTY	1		22 DIR DPM	1	
	23 OELD	1		AD/SITE TECH	1	
	DIRECTOR DSE	1		GEOSCIENCES BR	1	
	I&C SYS BR	1		MATL ENG BR	1	
	MECH ENG BR	1		POWER SYS BR	1	
	S HANAUER	1		STRUCT ENG BR	1	
EXTERNAL:	03 LPDR	1		04 NSIC	1	1
	24 ACRS	16	10			

DRAWGS TO:

FILES

ALL OTHER RECEIVE LTR'S

REPRODUCABLE ENCL ONLY

See drawing folder:

- 1) Storm Damage (7910250382)
- 2) Hurricane David Damage (7910250384)
- 3) Storm Damage (7910250386)
- 4) Storm Damage RAB (7910250391)
- 5) Storm Damage (7910250393)

OCT 29 1979

TOTAL NUMBER OF COPIES REQUIRED: LTR 47 ENCL 47

- 6) Storm Damage (7910250397)

MA 1



2

The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that every entry should be supported by a valid receipt or invoice. This ensures transparency and allows for easy verification of the data.

Furthermore, it is noted that the records should be kept up-to-date and organized in a systematic manner. This will facilitate the generation of reports and the identification of trends over time.

In addition, the document highlights the need for regular audits to ensure the integrity of the information. Audits help to detect any discrepancies or errors early on, preventing them from becoming major issues.

The second part of the document provides a detailed overview of the current financial status. It includes a summary of the total revenue generated and the corresponding expenses incurred. The net profit is calculated and compared against the previous period to assess performance.

The final section of the document offers recommendations for future actions. It suggests that the company should continue to invest in technology to improve efficiency and accuracy. Additionally, it advises on strategies for cost reduction and revenue growth.

Overall, the document serves as a comprehensive guide for managing financial data effectively. It provides valuable insights and practical advice that can be applied to various business contexts.



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
WASHINGTON, D. C. 20555

MEMORANDUM FOR: TERA Corp.

FROM: US NRC/TIDC/Distribution Services Branch

SUBJECT: Special Document Handling Requirements

1. Please use the following special distribution list for the attached document.

2. The attached document requires the following special considerations:

Do not send oversize enclosure to the NRC PDR.


Only one oversize enclosure was received - please return for Regulatory File storage.

Proprietary information - send affidavit only to the NRC PDR

Other: (specify)

cc: DSB Files

  
TIDC/DSB Authorized Signature



79-001-036

Burdette



October 4, 1979  
L-79-283

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

USNRC REGION II  
ATLANTA, GEORGIA  
19 OCT 10 P 2: 52

Dear Mr. O'Reilly:

Re: RII:JPO  
50-389  
DAMAGE RESULTING FROM DERRICK  
FAILURE DURING HURRICANE DAVID

As previously reported to the Office of Inspection and Enforcement on September 4 and 5, 1979, during the passage of Hurricane David the Chicago Bridge & Iron guyed derrick collapsed resulting in damage to the Reactor Auxiliary Building on elevations +43 feet and +62 feet, and the concrete Shield Building at elevation +191 feet.

Pursuant to 10CFR50.55(e) requirements, an interim report is attached with a copy also forwarded to Region IV, Office of Inspection and Enforcement. A final deficiency report will be filed by February 1, 1980.

Very truly yours,

*J. A. De Maskey*

Robert E. Uhrig  
Vice President

Attachment

cc: Director of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555  
(w/attachment)

3019  
5-11  
DRAWS TO:  
FILES  
ALL OTHERS RECEIVE  
LTR & REPRODUCER  
ENCL ONLY

7910250 374 OFFICIAL COPY