


ENRC RII
ANTA

11:40



FLORIDA POWER & LIGHT COMPANY

October 29, 1979

L-79-305

Central File
50-335

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII:JPO
50-335
IE Bulletin 79-13

Radiographic examination of three welds on each of the two main feedwater lines (nozzle to safe-end, safe-end to elbow, and elbow to piping) and visual inspections of feedwater piping restraints in containment were completed at St. Lucie Unit 1 by late September 1979. There were no reportable indications. Specific inspection results are available for review at the plant site.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/MAS:pg

cc: Harold Reis, Esquire

AOKI
2

7911210 006

PEOPLE SERVING PEOPLE
COPY

