



May 13, 1980  
L-80-152

USNRC RECEIVED  
MAY 13 1980

MAY 21 11:42

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

Re: RII: CAJ  
50-335/80-08

Florida Power & Light Company has reviewed the subject inspection report and a response is attached.

There is no proprietary information in the report.

Very truly yours,

Robert E. Uhrig  
Vice President  
Advanced Systems & Technology


REU/MAS/pa

Attachment

cc: Harold F. Reis, Esquire

OFFICIAL COPY

8006230166



ATTACHMENT

RESPONSE TO USNRC INSPECTION REPORT 80-08

Finding: As required by Technical Specification 3.9.2, during refueling operations, as a minimum, two wide range logarithmic flux monitors shall be operating, each with continuous visual indication in the control room and one with audible indication in the containment.

Contrary to the above, on April 1, 1980 during refueling operations, flux monitor indication was not audible in the containment.

Response: As described in Inspection Report 80-08, interim measures were taken to supply an audible flux count to the refueling area.

An engineering study is being requested to supply an amplified audible flux count to the refueling area. This plant modification will be installed and operable by the next refueling.

