

USNRC REGION II
ATLANTA, GEORGIA



30 SEP 17 A 9: 08

September 15, 1980
L-80-305

Central File

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

A0/a

Dear Mr. O'Reilly:

Re: RII:JPO
50-389
IE Bulletin 80-20

Florida Power & Light Company has reviewed IE Bulletin 80-20 regarding a failure of Westinghouse Type W-2 Spring Return to Neutral Control Switches. We are still in the process of investigating the extent of use (if any) of these control switches in safety related systems.

We expect to submit a complete response to this bulletin by November 14, 1980.

Very truly yours,

Robert E. Uhrig
Vice President
Advanced Systems & Technology

REU/TCG/ah

cc: U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Division of Reactor Operations Inspection
Washington, D. C. 20555

Harold F. Reis, Esquire

R.

OFFICIAL COPY

8009300 040

Q