

RECEIVED  
NOV 17 1980  
CENTRAL FILES  
P.O. BOX 529100 MIAMI, FL 33152  
FPL  
FLORIDA POWER & LIGHT COMPANY  
November 13, 1980  
L-80-379

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303

1012

Dear Mr. O'Reilly:

Re: RII:JPO  
50-389  
IE Bulletin 80-20

Ref: FPL Letter L-80-305 Dated September 15, 1980

Florida Power & Light Company has reviewed IE Bulletin 80-20 regarding a failure of Westinghouse Type W-2 spring return to neutral control switches. In the referenced letter, FPL advised the NRC that a final response would be issued upon receipt of information from all our vendors. That information is now complete. Although one vendor, Westinghouse, uses the Westinghouse Type W-2 switch in safety related circuits, the neutral position contact that is of concern in the Bulletin is not wired to any circuit. Therefore, IE Bulletin 80-20 is not applicable to St. Lucie Unit 2.

We consider this Bulletin closed.

Very truly yours,



Robert E. Uhrig  
Vice President  
Advanced Systems & Technology

REU/TCG/ah

cc: U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Division of Reactor Operations Inspection  
Washington, D. C. 20555  
Harold F. Reis, Esquire

8012080 588

 PEOPLE...SERVING PEOPLE

10/15

10/15

10/15