

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8102180672 DOC.DATE: 81/02/06 NOTARIZED: NO
 FACIL:50-335 St. Lucie Plant, Unit 1, Florida Power & Light Co.
 AUTH.NAME AUTHOR AFFILIATION
 PACE,P.L. Florida Power & Light Co.
 RECIPI.NAME RECIPIENT AFFILIATION
 Region 2, Atlanta, Office of the Director

DOCKET #
 05000335.

SUBJECT: LER 80-003/01T-0: on 810123 during full power operation, plant masonry wall re-evaluation showed missing clip angles & clip angle reinforcements, contrary to IE Bulletin 80-11 criteria. Caused by design error. Mods to wall completed by 810205.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+3
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	CLARK,R. 04	3	3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08	1	1	A/D OP REACTO09	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	ACC EVAL BR 14	1	1
	AEOD	3	3	ASLBP/J.HARD	1	1
	AUX SYS BR 15	1	1	CHEM ENG BR 16	1	1
	CONT SYS BR 17	1	1	CORE PERF BR 18	1	1
	DIR, DIV OF LIC	1	1	DIR, ENGINEER I20	1	1
	DIR, HUM FAC S21	1	1	DIR, SYS INTEG22	1	1
	EFF TR SYS BR23	1	1	EQUIP QUAL BR25	1	1
	GEOSCIENCES 26	1	1	I&C SYS BR 29	1	1
	I&E 05	2	2	JORDAN, E./IE	1	1
	LIC GUID BR 30	1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33	1	1	MPA	3	3
	NRG PDR 02	1	1	OP EX EVAL BR34	3	3
	OR ASSESS BR 35	1	1	POWER SYS BR 36	1	1
	RAD ASSESS BR39	1	1	REACT SYS BR 40	1	1
	REG FILE 01	1	1	REL & RISK A 41	1	1
	SFTY PROG EVA42	1	1	STRUCT ENG BR44	1	1
	SYS INTERAC B45	1	1			
EXTERNAL:	ACRS 46	16	16	LPDR 03	1	1
	NSIC 05	1	1	TERA: DOUG. MAY	1	1

FEB 19 1983

LB

