S) mai

ACCESSION NBR:8310270211 DOC.DATE: 83/10/21 NOTARIZED: NO FACIL:50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co.

DOCKET # 05000389

AUTHOR AFFILIATION WILLIAMS, J.W. Florida Power & Light Co.

RECIP.NAME EISENHUT,D.G. RECIPIENT AFFILIATION
Division of Licensing

SUBJECT: Forwards list of addl ESF actuation system lays not identified in 830926 submittal or FSAR to be testable w/o jeopardizing plant safety. Sufficient justification provided for not testing relays.

NOTES:

	RECIPIENT.		COPIES		RECIPIENT		COPIES	
	ID CODE/NAME		LTTR	ENCL	ID' CODE/NAM	<u> </u>	LTTR	ENCL
	NRR/DL/ADOR		" 1	0	NRR ORB3 BC	•	1	0
	KREUTZER, P		Ï.	0	SELLS,D	01	1 \	1
INTERNAL:	ELD/HDS2		1	0	IE FILE		1	1
	IE/DEPER/EPB	36 '	3	3	IE/DEPER/IRB	35	1	1
	IE/DEQA/QAB	21	ì	1	NRR/DE/AEAB	•	1	0
	NRR/DE/CEB	11,	1	1	NRR/DE/EHEB		1	1
	NRR/DE/EQB	13.	ã	'2	NRR/DE/GB	28	S	2
	•	18	ī	1	NRR/DE/MTEB	17	1	1
	NRR/DE/SAB	24	ī	i	NRR/DE/SGEB	25	1	1
	NRR/DHFS/HFEB		Ĩ.	1	NRR/DHFS/LQB	32	1	1
	NRR/DHFS/PSRE		ï	ĩ	NRR/DL/SSPB		1	0
	NRR/DSI/AEB	26	ï	ĩ	NRR/DSI/ASB		1.	1
	NRR/DSI/CPB	10	ï	ĩ		·09-	1	1
	NRR/DSI/ICSB		ī	1.	NRR/DSI/METB	12	î	ï
	NRR/DSI/PSB	19	. ī	. Î	NRR-LDS-I-LRAB	22	ï	1
	NRR/DSI/RSB	23.	ï	1	REG FILE	0.4	ï	ĩ
	RGN2		3	3	RM/DDAMI/MIB		1	Õ
EXTERNAL:	ACRS	41	6	6	BNL (AMDTS ONI	(Y)	1	1
	DMB/DSS (AMDT	-	ī	1	FEMA-REP DIV		1	1
	LPDR	03.	. 1	1	NRC PDR	02	1	1
	NSIC	05	1	ī	NTIS	-,	1	1

সংখ্যা কৰিছিল কি ত কৰিছিল কৈ তাৰ কৰিছিল কুটাৰ প্ৰকাশক কৰিছিল কুটাৰ প্ৰকাশক কৰিছিল কৰিছিল

EXAMPLE FROM STANDARD CONTRACTOR OF THE PROPERTY CONTRACTOR OF THE CONTRACTOR OF THE

30 98 31 4

17. 3	7 10	T # 81 81 13*	į,	8 100	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
1111	111	1 A Ct + 1A A	F 1 . 1	SHILL	RAA NAWY I
ú	ţ	東京 をおり × 間にな	0	ا ر	DV . M A JM, A DAYA H
1	R .	1	0	i.	41 4 2 4 4 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	1	* K - F I K *	i,	ĭ	SAMES VIE : JA PARTIE
	P	The Sunking of Kilder a	خر	r.	東京 - 14 17 1 14 14 14 14 14 14 14 14 14 14 14 14 1
1	ř	G () 1 () () () () () () ()	ţ.	X.	16 11 No 15 18 18 18
Î	,	41 62 / 4 / C3 31 M	1,0	A.	II I I I I I I I I I I I I I I I I I I
13	5	14 × 13 17 × 13 14 11	4,	33	El L'An Nich
1		OF FIXELENCE TRILL &	*	Ì	A NOTATION OF THE PARTY OF THE
	}	RT 1 19 10 EN 114 1151.	P)	i.	Mark Mark Start
•	Þ	* > HP ING INFOXED !	•	Ĭ.	WEST OF A CANADA STATE OF THE S
н	†	1198813019.01	•	Ř	1 (人) (人) (() () () () () () () (
ı	,	FEBANE PART IN	R	ž.	69 1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
į.	Į	W 183183 1140	*	¥	Merry (1811 19
	A	SE LE CONTRACTOR		۵.	CAT THE MENT OF THE
X	•	The state of the s	ņ	,ji	1 P 91 1 1 V (11) V - 57;
4	ř	P1 4 3 3 3 4	*		€ 6, 1 (1) (1) (1) (4) (4) (4)
K 4	¥	181 N 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1	ч) "tv:
1	•	Carlot all All All	•	*	Extended the same of
	t	/ VI THE HELL		ž.	K R KA CF AND VI
	it.	Kay " " 19 No.	*	Ī.	(C. S.)
	*	, ' ñ 1	•	à	8 3.80°



October 21, 1983 L-83-526

Office of Nuclear Reactor Regulation
Attention: Mr. Darrell G. Eisenhut, Director
Division of Licensing
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Eisenhut:

Re: St. Lucie Unit 2 Docket No. 50-389

ESFAS Actuation Relay Testing

References:

- 1) FPL Letter L-83-497 dated September 26, 1983 from Dr. R. E. Uhrig (FPL) to D. G. Eisenhut (DL)
- 2) NRC Letter dated June 7, 1983 from G. W. Knighton (DL/LB3) to Dr. R. E. Uhrig (FPL)

Per Reference 2, Florida Power & Light Co. (FPL) was requested to provide a list of specific ESFAS actuation devices (subgroup relays, initiation relays, etc.) that cannot be tested during plant power operation without jeopardizing plant safety or operability along with a justification why these devices cannot be tested. In addition, FPL was requested to provide information to verify that the actuated equipment assignments to each actuation device were made in a manner to minimize the number of components which cannot be tested at power.

Via Reference I, FPL submitted a table listing specific devices and their associated actuated equipment which cannot be tested at power. This list represented equipment that had not been previously identified in Table 7.3-9 of the St. Lucie Unit 2 FSAR.

Subsequent to the submittal of Reference I, plant personnel identified additional equipment whose actuation has the potential of causing a plant trip. It has been determined that actuating the 4.16 KV undervoltage interlock (located on test groups 7A and 7B) concurrent with an undervoltage condition on the 4.16 KV buses will cause a plant trip. Under voltage on the 4.16 KV buses will not trip the plant unless these interlocks are armed: This concern was identified to the NRC in a conference call held between FPL and NRC staff on September 30, 1983.

While the undervoltage interlocks had previously been identified as non-testable, the SIAS test groups 7A and 7B had not. To prevent arming these interlocks, SIAS test group 7A and 7B may not be tested. The attached table represents additional equipment that will be affected that had not been previously identified in either the FSAR or Reference I. FPL therefore considers sufficient justification is provided for not testing these components.

B310270211 B31021 PDR ADOCK 050003B9 PDR PDR Boo!

Page 2 Office of Nuclear Reactor Regulations Mr. Darrell G. Eisenhut, Director

Should you have any questions concerning this letter, please do not hesitate to contact us.

Very truly yours,


J. W. Williams, Jr. Vice President

Nuclear Energy Department

JWW/JEM/cab

J. P. O'Reilly, Region II

Harold F. Reis, Esquire



ESFAS Test Group	Actuation Device	Components Not Tested	Reason Not Tested At Power	Justification for Not Testing
SIAS 7A	K507A	Diesel Generator 2A	Actuating 4.16 KV UV Interlocks (also on SIAS 7A) may cause a plant trip.	Diesel Generator 2A is also started on CIAS 5A test group.
SIAS 7B	K607A	Diesel Generator 2B	Actuating 4.16 KV UV Interlocks (also on SIAS 7B) may cuase a plant trip.	Diesel Generator is also started on CIAS 5B test group.