

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8707060691 DOC. DATE: 87/07/01 NOTARIZED: NO DOCKET #
 FACIL: 50-335 St. Lucie Plant, Unit 1, Florida Power & Light Co. 05000335
 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co. 05000389
 AUTH. NAME AUTHOR AFFILIATION
 WOODY, C. D. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)


SUBJECT: Special rept: on 870528, cit water tank 1B declared inoperable
 for more that 7-days limited allowed by Tech Specs to
 preform necessary maint. Caused by sandblasting of tank inner
 shell & evaluated corrosion pitting.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 1	PD2-2 PD	1 1
	TOURIGNY, E	1 1		
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2
	AEOD/DOA	1 1	AEOD/DSP/ROAB	2 2
	AEOD/DSP/TPAB	1 1	DEDRO	1 1
	NRR/DEST/ADE	1 0	NRR/DEST/ADS	1 0
	NRR/DEST/CEB	1 1	NRR/DEST/ELB	1 1
	NRR/DEST/ICSB	1 1	NRR/DEST/MEB	1 1
	NRR/DEST/MTB	1 1	NRR/DEST/PSB	1 1
	NRR/DEST/RSB	1 1	NRR/DEST/SGB	1 1
	NRR/DLPQ/HFB	1 1	NRR/DLPQ/GAB	1 1
	NRR/DOEA/EAB	1 1	NRR/DREP/RAB	1 1
	NRR/DREP/RPB	2 2	NRR/PMAS/ILRB	1 1
	NRR/PMAS/PTSB	1 1	REG FILE 02	1 1
	RES DEPY GI	1 1	RES TELFORD, J	1 1
	RES/DE/EIB	1 1	RGN2 FILE 01	1 1
EXTERNAL:	EG&G GROH, M	5 5	H ST LOBBY WARD	1 1
	LPDR	1 1	NRC PDR	1 1
	NSIC HARRIS, J	1 1	NSIC MAYS, G	1 1

TOTAL NUMBER OF COPIES REQUIRED: LTTR 44 ENCL 42



JULY 1 1987

L-87-278
10 CFR 50.4

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555


Gentlemen:

Re: St. Lucie Units 1 and 2
Docket Nos. 50-335 and 50-389
Special Report
Date of Event: May 28, 1987
IB City Water Storage Tank

The attached Special Report is being transmitted pursuant to the requirements of Technical Specifications 3.7.11.1 and 6.9.2. The report provides notification that the IB City Water Storage tank was out of service for greater than seven (7) days and the actions taken to restore the tank to service.

Should there be any questions on this information, please contact us.

Very truly yours,


C. O. Woods
Group Vice President
Nuclear Energy

COW/GRM/gp

Attachment

cc: Dr. J. Nelson Grace, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, St. Lucie Plant

8707060691 870701
PDR ADDCK 05000335
S PDR

IE22
11

NRC SPECIAL REPORT

IB CITY WATER STORAGE TANK INOPERABLE FOR MAINTENANCE AS ALLOWED BY TECHNICAL SPECIFICATIONS

At 2351 hours on May 28, 1987, the IA City Water Storage Tank (CWST) was declared inoperable as part of scheduled repairs to be performed on the tank. Recent inspections of the IA and IB CWST performed on January 3, 1987, revealed that corrosion pitting was taking place on the interior shell of the tanks. The protective coating is beginning to deteriorate and small areas are exposed to the environment. This resulted in the pitting seen in the tanks. Even though the extent of the pitting was not of immediate concern for the structural integrity of the tanks, it was recommended to repair the tank protective coating system to prevent further corrosion. The IA CWST repairs were completed on January 27, 1987. A Special Report was previously submitted by FPL letter L-87-61, dated February 9, 1987.

In accordance with the St. Lucie Unit 1 and Unit 2 Technical Specification 3.7.11.1, this Special Report is being submitted to notify the NRC that the IB CWST has been inoperable for greater than the allowed seven (7) days. The following is the plan to restore the equipment to operable status. The reason for declaring the equipment inoperable was the maintenance repair on the IB CWST. The tank inner shell has been sandblasted and the corrosion pitting has been evaluated by FPL Engineering and Chicago Bridge Incorporated. Weld repairs are being performed and the protective coating will be applied as soon as weld repairs are completed. The expected completion date of the tank repair is July 15, 1987. The IA CWST has remained operable to supply the redundant fire suppression system while the IB CWST is undergoing repairs.