

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-335
 UNIT NAME ST. LUCIE #1
 DATE 8/13/90
 COMPLETED BY J. W. HOLT
 TELEPHONE 407-465-3550

** CORRECTED COPY **

REPORT MONTH JULY 1990

9008280280 900820 900820
 PDR ADCK 05000335
 PDC

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
09	900702	F		A	5	N/A	CA	PUMPXX	Unit 1 reduced power for RCP seal leakage.
10	900702	F	706.7	A	1	N/A	CA	PUMPXX	Unit 1 taken off line to repair a leaking RCP seal.

1
 F Forced
 S Scheduled

2
 Reason
 A - Equipment Failure (Explain)
 B - Maintenance or Test
 C - Refueling
 D - Regulatory Restriction
 E - Operator Training & License Examination
 F - Administrative
 G - Operational Error (Explain)
 H - Other (Explain)

3
 Method
 1 - Manual
 2 - Manual Scram
 3 - Automatic Scram
 4 - Continued
 5 - Load Reduction
 9 - Other (Explain)

4
 Exhibit G-Instructions for Preparation of Data Entry Scheets Licensee Event Report (LER) File (NUREG-0161)

5
 Exhibit 1 - Same Source



UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50-389
 UNIT NAME ST. LUCIE #2
 DATE 8/13/90
 COMPLETED BY J. W. HOLT
 TELEPHONE 407-465-3550

** CORRECTED COPY **

REPORT MONTH JULY 1990

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report #	System Code ⁴	Component Code ⁵	Cause & Corrective Action to Prevent Recurrence
07	900726	S		B	5	N/A	HF	TURBIN	Unit 2 reduced power for condenser waterbox cleaning.

1
 F Forced
 S Scheduled

2
 Reason
 A - Equipment Failure (Explain)
 B - Maintenance or Test
 C - Refueling
 D - Regulatory Restriction
 E - Operator Training & License Examination
 F - Administrative
 G - Operational Error (Explain)
 H - Other (Explain)

3
 Method
 1 - Manual
 2 - Manual Scram
 3 - Automatic Scram
 4 - Continued
 5 - Load Reduction
 9 - Other (Explain)

4
 Exhibit G- Instructions for Preparation of Data Entry Scheets Licensee Event Report (LER) File (NUREG-0161)
5
 Exhibit 1 - Same Source

SUMMARY OF OPERATING EXPERIENCE

** Corrected Copy **

DOCKET NO. 50-335

UNIT St. Lucie #1

DATE 8/13/90

COMPLETED BY J. W. Holt

TELEPHONE (407) 465-3550

REPORT MONTH JULY, 1990

On July 2, 1990 Unit 1 had a power reduction and was taken off line due to a Reactor Coolant Pump (RCP) seal leak. The unit was off line the remainder of the month for RCP seal repair.

In accordance with the requirements of Technical Specification 6.9.1.6, there were no challenges to the PORVs or safety valves during the report period.