



Richard D Bologna Site Vice President 724-682-5234 Fax: 724-643-8069

August 18, 2017 L-17-240

10 CFR 50.55a(g)

ATTN: Document Control Desk U. S. Nuclear Regulatory Commission Washington, DC 20555-0001

SUBJECT:

Beaver Valley Power Station, Unit No. 2 Docket No. 50-412, License No. NPF-73 Nineteenth Refueling Outage Inservice Inspection Summary Report

In accordance with 10 CFR 50.55a, "Codes and standards," and the American Society of Mechanical Engineers Boiler and Pressure Vessel Code Section XI, Article IWA-6000, "Records and Reports," and ASME Code Case N-532-5, enclosed please find the inservice inspection summary report for examinations performed prior to and during the nineteenth refueling outage at Beaver Valley Power Station, Unit No. 2 (BVPS-2).

Class 1, 2, 3, and IWE component inservice inspection examinations addressed in the report are part of the BVPS-2 third period of the third ten-year interval and were performed in accordance with Section XI of the ASME Boiler and Pressure Vessel Code, 2001 Edition, 2003 Addenda. The inservice inspection term at BVPS-2 covered by this report includes the period from October 31, 2015 to May 21, 2017

There are no regulatory commitments contained in this submittal. If there are any questions or if additional information is required, please contact Mr. Thomas A. Lentz, Manager - Fleet Licensing, at 330-315-6810.

Sincerely,

Richard D. Bologna

Beaver Valley Power Station, Unit No. 2 L-17-240 Page 2 of 2

Enclosure:

Beaver Valley Power Station, Unit No. 2, Nineteenth Refueling Outage Inservice Inspection Summary Report

cc: NRC Region I Administrator NRC Resident Inspector NRC Project Manager Director BRP/DEP Site BRP/DEP Representative

Enclosure L-17-240

Beaver Valley Power Station, Unit No. 2 Nineteenth Refueling Outage Inservice Inspection Summary Report

(3 Pages Follow)

Beaver Valley Power Station Unit 2 Inservice Inspection Program 2R19 Owner's Activity Report



Report No.

BV2-OAR1-2R19

6/6/2017

1 of 3

FORM OAR-1 OWNER'S ACTIVITY REPORT					
D. W. CADA 0D40					
Report Number BV2-OAR1-2R19					
Plant Beaver Valley Power Station					
Unit No. 2 Commercial Service Date	November 17, 1987 Refueling Outage No. 2R19				
Current Inspection Interval					
^	(1 ^{nt} , 2 nd , 3 rd , 4 th , other)				
Current Inspection Period 3 rd	(1 st , 2 nd , 3 rd)				
Edition and Addenda of Section XI applicable to the inspection plan	2001 Ed. / 2003 Add.				
Date and Revision of inspection plans 9/15/15, ADM-2039, Rev.	15				
Edition and Addenda of Section XI applicable to repair/replacement ac	tivities, if different than the inspection plans Same				
Code Case Used: N-460, N-532-5, N-566-2, N-722-1, N-729-1, (if applicable, including	N-770-1 cases modified by Case N-532 and later revisions)				
CERTIFICATE O	FCONFORMANCE				
I certify that (a) the statements made in this report are correct; (b)	the examinations and tests meet the Inspection Plan as required by the				
ASME Code, Section XI; and (c) the repair/replacement activities					
conform to the requirements of Section XI.	(refueling outage number)				
Signed D. Grabski Dorab Priyana	ner Date 6-28-17				
Signed D. Grabski Down TripmOn * L. P. Seamer Owner's Designee, Title * Progre	mouner 7/24/17				
CERTIFICATE OF INSERVICE INSPECTION					
I, the undersigned, holding a valid commission issued by the N	lational Board of Boiler and Pressure Vessel Inspectors and				
employed by Hartford Steam Boiler of Inspection and Insurance Company	Hartford, have inspected the items described in the Connecticut				
Owner's Activity Report, and state that, to the best of my knowled by this report in accordance with the requirements of Section XI. By signing this certificate neither the Inspector nor his employ repair/replacement activities and evaluation described in this report liable in any manner for any personal injury or property damage of	er makes any warranty, expressed or implied, concerning the t. Furthermore, neither the Inspector nor his employer shall be r a loss of any kind arising from or connected with this inspection.				
Jacal C. Schell Commission Inspector's Signature	NB 7920 ANIB (National Board Number and Endorsement)				
Date 7-6-2017					



Report No. BV2-OAR1-2R19

6/6/2017

2 of 3

TABLE 1 ITEMS WITH FLAWS OR RELEVANT CONDITIONS THAT REQUIRED EVALUATION FOR CONTINUED SERVICE

Examination Category and Item Number	Item Description	Evaluation Description
None	N/A	N/A

TABLE 2 ABSTRACT OF REPAIR/REPLACEMENT ACTIVITIES REQUIRED FOR CONTINUED SERVICE

Code Class	Item Description	Description of Work	Date Completed	Repair/Replacement Plan Number
2	2CVS-SOV151A	Tack weld body to bonnet	5/18/2017	3101
2	2CVS-SOV152A	Tack weld body to bonnet	5/18/2017	3102
		Replaced stuffing box extension,		
2	2RHS-P21A	mechanical seal flange, studs/nuts	5/17/2017	3139
3	2CCP-AOV174	Replaced valve plug	5/12/2017	3661
2	2MSS-SV101C	Replaced valve, nozzle, inlet stud	5/18/2017	3693
2	2MSS-SV102C	Replaced valve	5/18/2017	3697
2	2MSS-SV103C	Replaced valve	5/18/2017	3698
2	2MSS-SV104C	Replaced valve	5/18/2017	3699
2	2MSS-SV105C	Replaced valve, disc insert	5/18/2017	3700
3	2SWS-906	Replaced valve, pipe	5/22/2017	3801
3	2CHS-50	Replace valve	5/5/2017	3932
3	2HVC-CND24A	Repaired inlet spoolpiece flange	2/25/2016	3934
3	2CCP-21C	Replaced gland ring	11/28/2016	3946
1	2SIS-545	Replaced disc assembly	5/18/2017	3947
3	2SWS-186	Replaced valve, studs/nuts	5/19/2017	3957
3	2SWS-189	Replaced valve, studs/nuts	5/19/2017	3958
1	2RCS-RV551A	Replaced valve, studs/nuts	5/23/2017	3960
3	2CCP-304	Replace valve	5/18/2017	3969
1	2RCS-PSSP030	Replace snubber	5/12/2017	3970
2	2CHS-P21B	Replaced seal housing	8/18/2016	3971
3	2SWE-MOV116B	Replaced valve, studs/nuts	5/19/2017	3987
3	2SWS-107	Replace valve	6/22/2017	3989
2	2-CHS-150-674-2	Removed valve 2CHS-RV450A and installed blind flange, studs/nuts	5/19/2017	3996
2	2RHS-RV721A	Replaced valve	5/17/2017	3997
3	2FWE-PSSP354A	Replaced snubber	5/12/2017	3998
3	2FWE-PSSP354B	Replaced snubber	5/15/2017	3999
1	2CHS-PSSP015X	Replace snubber	5/12/2017	4001
1	2RCS-SG21A	Installed mechanical plugs, sleeves	5/12/2017	4003
1	2RCS-SG21B	Installed mechanical plugs, sleeves	5/12/2017	4004

Beaver Valley Power Station Unit 2 Inservice Inspection Program 2R19 Owner's Activity Report



Report No.

BV2-OAR1-2R19

6/6/2017

3 of 3

Code Class	Item Description	Description of Work	Date Completed	Repair/Replacement Plan Number
1	2RCS-SG21C	Installed mechanical plugs	5/12/2017	4005
2	2RHS-E21A	Replace stud	6/22/2017	4010
3	2RCS-P21B-MOTOR	Replaced motor/coolers	5/22/2017	4013
1	2RCS-PCV456	Replaced plug	5/22/2017	4015
3	2-FWE-002-203-3	Replace pipe/fitting	6/5/2017	4016