

James G. Juppier, Regional Director
Directorate of Regulatory Operations
Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Televised

Date

7-28-75

GR

DC

11:14 A.M.

By

cc:

Bernard C. Rusche, Director
Directorate of Licensing
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

NO 50' 249/75-32

SUBJECT: DPR-AS, Dresden Nuclear Power Station, Unit 3

This will confirm a conversation with Mr P Johnson of your office at 0820 hrs this date concerning LOCATION OF SLOTTED TAKE WELDS ON SET PUMP RESTRAINER CLAMP BOLT KEEPERS DURING TV CAMERA EXAMINATION OF UNIT 3 SET PUMPS #6 AND #17. STRUCTURAL INTEGRITY OF THE SET PUMPS WERE FOUND SATISFACTORY AND NO PARTS WERE BROKEN LOOSE FROM THE RETAINER. ONLY ONE OF THE TWO CLAMP BOLT KEEPERS ON EACH SET PUMP WERE AFFECTED. REPAIR WILL CONSIST OF UNDERWATER TAKE WELDING OF THE KEEPERS IN PLACE FOLLOWING TORQUE MEASUREMENTS OF THE CLAMP BOLTS IS FOUND SATISFACTORY.

To Call:

GE - 5-858-2660x16 (auto) - on 6
DC - 9-1-301-492-7617 (auto)
WU - 815-942-4449/4321

Station Dist: Originator (copy)
Incident File (copy)

B. B. Stephenson, Superintendent
Dresden Nuclear Power Station
Commonwealth Edison Company
E.R. #1
Morris, IL 60450

Telephone: 815-642-2020/2021-212