



western union

Telegram

NKA578(2005)(1-057052A159)PD 06/08/73 2002

ICS IPMDCNC NYK

03138 FR DC NEWYORK NY 185 06-08 618P EDT

PMS JAMES P OREILLY DIR

REGULATORY OPERATIONS REGION I

US ATOMIC ENERGY COMMISSION

970 BROAD ST

NEWARK NJ 07102

RE: INDIAN POINT UNIT #2 -FACILITY OPERATING

LICENSE DPR-26

IN ACCORDANCE WITH THE REQUIREMENTS OF TECHNICAL SPECIFICATION

6.6.1.B,

WE WISH TO INFORM YOU OF AN ABNORMAL OCCURRENCE,

(A.O. 3-2-8)

WHICH TOOK PLCE ON JUNE 7 1973.

SF-1201 (R5-69)



western union

Telegram

DURING THE COURSE OF PERFORMING PERIODIC TESTS AND CALBBRATION CHECKS RELATING TO REACTOR COOLANT FLOW AS REQUIRED BY THE FACLLITY TECHNICAL SPECIFICATIONS,

IT WAS DETERMINED THAT THE FLOW TRIP SETTINGS WERE SLIGHTLY BELOW THOSE SPECIFIED IN SPECIFICATION 2.3.1.

AT THE TIME OF THE OCCURENCE, THE REACTOR WAS CRITICAL AT ZERO P OWER FOR ZERO POWER PHYSICS TESTING.

IN ACCORDANCE WITH THE REQUIREMENTS OF TECHNICAL SPECIFICATION 6.2, NOTIFICATION OF THE CHAIRMAN OF THE NUCLEAR FACILITIES AFETY COMMITTEE HAS TAKEN PLACE.

MR A FASANO OF YOUR OFFICE WAS ALSO NOTIFIED BY TELEPHONE ON JUNE 8 1973 OF THE OCCURENCE BY MR JOHN M MAKEPEACE, CHIEF ENGINEER, UNIT NO 2

SF-1201 (R5-69)



western union

Telegram

WE ARE CURRENTLY INVESTIGATING THE CAUSE OF THE OCCURRENCE
AND THE RESULTS OF OUR INVESTIGATION AND CORRECTIVE ACTION
TAKEN WILL BE SUBMITTED IN THE REQUIRED TEN DAY REPORT
TO THE DIRECTOR OF LICENSING

WILLIAM E CALDWELL-

CON EDISON CO

4 IRVING PLACE

NY NY 10003

TELEX NBR 12 7339