

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE NYREGI, LICENSE NUMBER 00000000000, LICENSE TYPE 41111, CAT 58

REPORT SOURCE L, DOCKET NUMBER 05000244, EVENT DATE 070979, REPORT DATE 080879

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES: During RCS cooldown, operator noted chan P-452 overpressurization alarm was not in correct state. Investigation showed power operator relief valve actuation bistable setpoint 8 psi above T.S. value. (T.S. 3.15.1a). Two redundant channels were operable.

SYSTEM CODE IE, CAUSE CODE E, COMPONENT CODE INSTRU, COMP. SUBCODE S, VALVE SUBCODE Z, LER/RO REPORT NUMBER 019, EVENT YEAR 79, SEQUENTIAL REPORT NO. 014, OCCURRENCE CODE 03, REPORT TYPE L, REVISION NO. 0, ACTION TAKEN C, FUTURE ACTION Z, EFFECT ON PLANT Z, SHUTDOWN METHOD Z, HOURS 0000, ATTACHMENT SUBMITTED N, NPRD-4 FORM SUB. Y, PRIME COMP. SUPPLIER L, COMPONENT MANUFACTURER F180

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS: Bistable setpoint drift. Alarm unit was replaced with qualified spare, alarm setpoint was adjusted, and unit was tested successfully. Unit was rechecked successfully on 7/16/79. The alarm unit is a Foxboro model 63/U-AT-OHAA.

FACILITY STATUS D, % POWER 000, OTHER STATUS NA, METHOD OF DISCOVERY B, DISCOVERY DESCRIPTION Operator observation

ACTIVITY CONTENT RELEASED OF RELEASE Z, AMOUNT OF ACTIVITY NA, LOCATION OF RELEASE NA

PERSONNEL EXPOSURES NUMBER 000, TYPE Z, DESCRIPTION NA

PERSONNEL INJURIES NUMBER 000, DESCRIPTION NA

LOSS OF OR DAMAGE TO FACILITY TYPE Z, DESCRIPTION NA

PUBLICITY ISSUED N, DESCRIPTION NA

NAME OF PREPARER E. Clair Edgar

7908140 800 J, PHONE: 716/546-2700, ext.291-248

