

LICENSEE EVENT REPORT

CONTROL BLOCK: [] [] [] [] [] [] [] []

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

CONT

CONT 1
REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 5 | 7 | 0 | 7 | 2 | 4 | 8 | 0 | 8 | 0 | 1 | 8 | 2 | 5 | 8 | 0 | 9 |
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

- 012** | While at 100% power, CEA #63 dropped to the fully inserted position.

013 | Action was initiated per T.S.3.1.3:le. Power was reduced to 65% and

014 | CEA #63 was realigned with the other CEA's in its group. This is the

015 | first dropped CEA due to maintenance activity.

0 15

0 7

013

CC904 CC905 CC906 CC907 CC908 CC909 CC910 CC911 CC912 CC913 CC914 CC915 CC916

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

- 10 | The dropped CEA was caused by a technician accidentally shorting the output
11 | of the 15 volt power supply while taking routine voltage measurements.
12 | These measurements, intended to detect failing supplies before failure,
13 | have been discontinued due to the close quarters and risk of shorting
14 | these supplies.

7 2 9
FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (52)
1 5 E (23) 1 0 0 (29) NA A (31) OPERATOR OBSERVATION

ACTIVITY CONTENT
RELEASED OR RELEASE
AMOUNT OF ACTIVITY (35)
1 5 Z (33) Z (34) NA
7 3 9 10 11 44

PERSONNEL EXPOSURES		TYPE	DESCRIPTION	④
NUMBER				
1	7	1	0	0
7	5	3	11	12
			13	

PERSONNEL INJURIES
NUMBER DESCRIPTION (41)
1 3 0 0 0 40 NA
7 3 9 11 12

LOSS OF CR DAMAGE TO FACILITY (43)
TYPE DESCRIPTION NA

NRC USE ONLY

NAME OF PREPARED P.L. Pace

PHONE: (305) 552-3801